



Approved CR

IAA Columbus
1601 Thrailkill Road
Branch No 662
Grove City, OH 43123
(614) 875-7484/(614) 875-7277
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 FORD
TRANSIT
CONNECT**

Bodystyle/Series: **- XL**

Color: **Yellow**

Mileage: **17,992
(Verified)**

Turn-in Mileage: **-**

VIN: **NM0GE9E78H1326965**

Work Order/
Stock Number: **46434536**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G411974U**

Vehicle Grade : **Grade 3.8**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 215 / 55 R 16

Car Tire Size - RF 215 / 55 R 16

Car Tire Size - LF 215 / 55 R 16

Car Tire Size - LR 215 / 55 R 16

LF Tires - 10/32 inch

LR Tires - 8/32 inch

RF Tires - 10/32 inch

RR Tires - 8/32 inch

Tire Brand - Front Left - MASTERCRAFT

Tire Brand - Front Right - MASTERCRAFT

Tire Brand - Rear Left - CONTINENTAL

Tire Brand - Rear Right - CONTINENTAL

Tire Model - LF - LSR Grand Touring

Tire Model - LR - Contiprocontact

Tire Model - RF - LSR Grand Touring

Tire Model - RR - Contiprocontact

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Warning - Tire Pressure	On	-	Unacceptable
	Rear Bumper	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Bumper Cover Upper	Oxidized	-	> 12 Inches
	Vinyl Floor	Torn	-	6 To 7 Inches
	Right Drip Rail Molding	Missing	-	Replacement Required
	Left Drip Rail Molding	Missing	-	Replacement Required
	Left Front Wheel Cover	Curb Rash	-	2 To 3 Inches
	Right Front Wheel Cover	Peeling	-	5 To 6 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Head Lamp	Faded	-	Repair Required
	Right Head Lamp	Faded	-	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.