



Approved
CR

IAA Metro DC
14149 Brandywine Rd
Brandywine, MD 20613
(301) 372-8876/(301) 372-8285
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 RAM
PROMASTER 1500**

Bodystyle/Series: **Cargo Van LOW
ROOF 136 WB**

Color: **White**

Mileage: **68,731 (Verified)**

Turn-in Mileage: **-**

VIN: **3C6TRVAG4JE153248**

Work Order/
Stock Number: **46388167**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G41-1652V**

Vehicle Grade : **Grade 3.2**

Remarks: **-**

Announcements: **• ANNOUNCEMENTS:**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /WHITE	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 225 / 75 R 16	Car Tire Size - RF 225 / 75 R 16	Car Tire Size - LF 225 / 75 R 16
Car Tire Size - LR 225 / 75 R 16	LF Tires - 8/32 inch	LR Tires - 10/32 inch
RF Tires - 9/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - TOYO
Tire Brand - Front Right - TOYO	Tire Brand - Rear Left - TOYO	Tire Brand - Rear Right - TOYO
Tire Model - LF - Open Country H/T	Tire Model - LR - Open Country H/T	Tire Model - RF - Open Country H/T
Tire Model - RR - Open Country H/T		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
-------	------	--------	--------	----------

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Wheel	Corrosion	-	> 12 Inches
	Rear Ls Panel	Chipped	-	2
	Left Rear Wheel	Corrosion	-	1 To 2 Inches
	Left Front Wheel	Corrosion	-	4 To 5 Inches
	Left Drip Rail	Chipped	-	2
	Inside Bed	Multiple Scratches Heavy	-	10 Or More

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Door	Multiple Scratches Light	-	3
	Hood	Chipped	-	3
	Left Headlamp Mounting Panel	Chipped	-	2
	Right Rear Door	Multiple Scratches Heavy	-	5
	Right Rear Cargo Door	Multiple Scratches Heavy	-	3
	Right Rear Wheel	Curb Rash	-	2 To 3 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.