



Approved CR

IAA Milwaukee
N70W25277 Indian Grass Lane
Branch No 521
Sussex, WI 53089
(262) 246-8822/(262) 246-4411
WHOLESALE ASSESSMENT ONLY

Make/Model: **2014 DODGE
GRAND
CARAVAN**

Bodystyle/Series: **Van SE**

Color: **Black**

Mileage: **45,327
(Verified)**

Turn-in Mileage: **-**

VIN: **2C4RDGBG2ER355506**

Work Order/
Stock Number: **46393059**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G412286U**

Vehicle Grade : **Grade 3.2**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Soft Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LR 225 / 65 R 17

Car Tire Size - RR 225 / 65 R 17

Car Tire Size - RF 225 / 65 R 17

Car Tire Size - LF 225 / 65 R 17

LF Tires - 9/32 inch

LR Tires - 10/32 inch

RF Tires - 9/32 inch

RR Tires - 10/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE


Tire Model - LF - Destination LE2

Tire Model - LR - Destination LE2

Tire Model - RF - Destination LE2

Tire Model - RR - Destination LE2

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Lf Strut	Rust	-	Severe Damage

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rf Strut	Rust	-	Severe Damage
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof	Chipped	-	3
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Left Front Wheel	Corrosion	-	> 12 Inches
	Left Rear Wheel Cover	Curb Rash	-	2 To 3 Inches
	Lift Gate	Multiple Scratches Heavy	-	2

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Rear Wheel	Corrosion	-	> 12 Inches
	Hood	Chipped	-	2
	Right Front Wheel	Corrosion	-	> 12 Inches
	Right Head Lamp	Faded	-	Repair Required
	Left Head Lamp	Faded	-	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.