



Approved CR

IAA Metro DC
14149 Brandywine Rd
Brandywine, MD 20613
(301) 372-8876/(301) 372-8285
WHOLESALE ASSESSMENT ONLY

Make/Model: **1998 CHEVROLET C1500**
Bodystyle/Series: **- FLEETSIDE**
Color: **White**
Mileage: **85,514 (Verified)**
Turn-in Mileage: **-**
VIN: **1GCEC14W4WZ233725**
Work Order/
Stock Number: **46380716**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**
Client Stock #: **G413336Z**
Vehicle Grade : **Grade 1.9**
Remarks: **-**
Announcements:

- Announcement:
Consolidated
unit No Repair
History

Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission w/ Overdrive	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	No
Engine Size:	4.3 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	Vinyl Interior /-	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	No
Seats:	Bench	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 235 / 75 R 15	Car Tire Size - LR 235 / 75 R 15	Car Tire Size - RR 235 / 75 R 15
Car Tire Size - RF 235 / 75 R 15	LF Tires - 7/32 inch	LR Tires - 7/32 inch
RF Tires - 5/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - BFGOODRICH	Tire Brand - Rear Left - BFGOODRICH	Tire Brand - Rear Right - BFGOODRICH
Tire Model - RR - Wrangler Radial	Tire Model - RF - Wrangler Radial	Tire Model - LR - Wrangler Radial
Tire Model - LF - Wrangler Radial		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Turn Signal	Misaligned	-	Repair Required
	Left Front Fender	Chipped	-	7
	Grille	Broken	-	Replacement Required
	Hood	Rust	-	1/2 To 1 Inch
	Rf Mirror Cover	Multiple Scratches Heavy	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Door	Heavy Scratch	-	7 To 8 Inches
	Right Cab Side	Dent(S) W/ Paint Dmg	-	2 To 3 Inches
	Dash	Broken	-	Replacement Required
	Right Head Lamp	Misaligned	-	Repair Required
	Right Bed Side	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Bed Side	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Cab - Left	Multiple Scratches Heavy	-	2
	Left Front Door	Dent(S) W/ Paint Dmg	-	5 To 6 Inches
	Roof	Chipped	-	1
	Steering Wheel	Worn	-	Replacement Required
	Tailgate	Mismatched	-	Unacceptable

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Marker Lamp	Broken	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.