



Approved CR

IAA Des Moines
1000 Armstrong Dr
Branch No 536
De Soto, IA 50069
(515)823-0600/(515)823-0626
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 DODGE
GRAND
CARAVAN**

Bodystyle/Series: **Van SE**

Color: **Silver**

Mileage: **116,944
(Verified)**

Turn-in Mileage: **-**

VIN: **2C4RDGBG7KR639242**

Work Order/
Stock Number: **46385273**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G41-0073W**

Vehicle Grade : **Grade 2.8**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	No
Engine Size:	3.6 L	Pwr Steering:	No
Roof:	-	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	- /BLACK	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	No
Seats:	-	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	-

Equipment

Additional Equipment:

Car Tire Size - LF 225 / 65 R 17

Car Tire Size - LR 225 / 65 R 17

Car Tire Size - RR 225 / 65 R 17

Car Tire Size - RF 225 / 65 R 17

LF Tires - 3/32 inch

LR Tires - 7/32 inch

RF Tires - 3/32 inch

RR Tires - 8/32 inch

Tire Brand - Front Left - GENERAL

Tire Brand - Front Right - GENERAL

Tire Brand - Rear Left - GENERAL

Tire Brand - Rear Right - GENERAL

Tire Model - RR - Altimax RT45

Tire Model - RF - Altimax RT45


Tire Model - LR - Altimax RT45

Tire Model - LF - Altimax RT45

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Lf Strut	Rust	-	Severe Damage
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Rf Strut	Rust	-	Severe Damage

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Wheel	Corrosion	-	> 12 Inches
	Left Front Wheel Cover	Curb Rash	-	1/2 To 1 Inch

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Tire	Worn	-	Replacement Required
	Steering Wheel	Worn	-	Replacement Required
	Left Front Door	Scuffed	-	1/8 To 1/2 Inch
	Rear Wiper Arm	Bent	-	Replacement Required
	Right Front Tire	Worn	-	Replacement Required
	Right Front Wheel	Corrosion	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Dent(S) W/No Paint Dmg	-	2 To 3 Inches
	Front Bumper	Chipped	-	6
	Hood	Chipped	-	3
	Right Rear Door	Chipped	-	2
	Right Rear Wheel	Corrosion	-	> 12 Inches
	Left Rear Wheel	Corrosion	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.