



Approved CR

IAA Des Moines
1000 Armstrong Dr
Branch No 536
De Soto, IA 50069
(515)823-0600/(515)823-0626
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 FORD
FUSION
HYBRID**

Bodystyle/Series: **4 Door Sedan
SE**

Color: **Silver**

Mileage: **125,523
(Verified)**

Turn-in Mileage: **-**

VIN: **3FA6P0LU7KR211547**

Work Order/
Stock Number: **46385327**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G10-0092W**

Vehicle Grade : **Grade 3.7**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Continuously Variable Transmission	A/C:	No
Engine:	4-Cylinder Hybrid	Cruise Control:	No
Engine Size:	2 L	Pwr Steering:	No
Roof:	-	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	- /BLACK	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	No
Seats:	-	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	-

Equipment

Additional Equipment:

Car Tire Size - LF 225 / 50 R 17

Car Tire Size - LR 225 / 50 R 17

Car Tire Size - RR 225 / 50 R 17

Car Tire Size - RF 225 / 50 R 17

LF Tires - 6/32 inch

LR Tires - 8/32 inch

RF Tires - 8/32 inch

RR Tires - 8/32 inch

Tire Brand - Front Left - KENDA

Tire Brand - Front Right - KENDA

Tire Brand - Rear Left - KENDA

Tire Brand - Rear Right - KENDA


Tire Model - RR - Vezda Touring A/S (KR205)

Tire Model - RF - Vezda Touring A/S (KR205)

Tire Model - LR - Vezda Touring A/S (KR205)

Tire Model - LF - Vezda Touring A/S (KR205)

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Lf Strut	Rust	-	Severe Damage
	Photo - Vin/Id Sticker	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	2
	Front Bumper Left Molding	Broken	-	Replacement Required
	Right Front Wheel	Curb Rash	-	3 To 4 Inches
	Right Qtr Panel	Chipped	-	2
	Right Rear Wheel	Curb Rash	-	3 To 4 Inches
	Left Rear Wheel	Curb Rash	-	1 To 2 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Roof	Dent(S) W/No Paint Dmg	-	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.