




Approved
CR

IAA Tidewater
211 Production Drive
Branch No 725
Yorktown, VA 23693
(757) 595-8493/(757) 595-8691
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD
FUSION HYBRID**
Bodystyle/Series: **4 Door Sedan S**
Color: **Silver**
Mileage: **1 (Unverified)**
Turn-in Mileage: **-**
VIN: **3FA6P0UU5JR254622**
Work Order/
Stock Number: **45741422**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G102584V**
Vehicle Grade : **Grade 1.6**
Remarks: **-**
Announcements:

**• ANNOUNCEMENTS:
SALVAGE Title**

Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: No

Equipment

Transmission:	Continuously Variable Transmission	A/C:	No
Engine:	4-Cylinder Hybrid	Cruise Control:	No
Engine Size:	2 L	Pwr Steering:	No
Roof:	-	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	- /-	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	No
Seats:	-	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	-

Equipment

Additional Equipment:

Car Tire Size - LF 225 / 50 R 17

Car Tire Size - LR 225 / 50 R 17

Car Tire Size - RR 225 / 50 R 17

Car Tire Size - RF 225 / 50 R 17

LF Tires - 8/32 inch

LR Tires - 7/32 inch

RF Tires - 8/32 inch

RR Tires - 8/32 inch

Tire Brand - Front Left - MICHELIN

Tire Brand - Front Right - MICHELIN

Tire Brand - Rear Left - MICHELIN

Tire Brand - Rear Right - MICHELIN

Tire Model - RR - Energy Saver A/S

Tire Model - RF - Energy Saver A/S

Tire Model - LR - Energy Saver A/S

Tire Model - LF - Energy Saver A/S

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Core Support	Broken	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Wheel	Curb Rash	-	1/2 To 1 Inch
	Left Front Fender	Multiple Dents/Paint Damage	-	2
	Right Rear Wheel	Curb Rash	-	1/2 To 1 Inch
	Right Front Wheel	Curb Rash	-	1 To 2 Inches
	Right Front Fender	Dent(S) W/ Paint Dmg	-	> 12 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Head Lamp	Missing	-	Replacement Required
	Radiator	Broken	-	Replacement Required
	Hood	Severe Damage	-	Replacement Required
	Grille	Missing	-	Replacement Required
	Front Bumper	Missing	-	Replacement Required
	Right Head Lamp	Misaligned	-	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.