



Approved
CR

IAA Albany
1210 Kings Road
Branch No 631
Schenectady, NY 12303
(518) 347-3810/(518) 346-0351
WHOLESALE ASSESSMENT ONLY

Make/Model: **2013 FORD F-750**
 Bodystyle/Series: - -
 Color: **White**
 Mileage: **22,376 (Verified)**
 Turn-in Mileage: -
 VIN: **3FRWF7FJ6DV798182**
 Work Order/
 Stock Number: **46368075**
 Customer: GSA Fleet Vehicle Sales
 1800 F Street NW
 Washington, DC 20405
 fleetsalesupport@gsa.gov
 Client Stock #: **G82-0329Y**
 Vehicle Grade : **Grade 3.1**
 Remarks: -
 Announcements:

• ANNOUNCEMENTS:
Rust /Corrosion

 Certification : -
 Req. Prev. Repair -
 Order:



Drivable: Yes

Equipment

Transmission:	-	A/C:	Yes
Engine:	6-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	6.7 L	Pwr Steering:	Yes
Roof:	Coach	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	Synthetic Leather /-	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Air Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 0 / 11 R 22.5	Car Tire Size - RF 0 / 11 R 22.5	Car Tire Size - LF 0 / 11 R 22.5
Car Tire Size - LR 0 / 11 R 22.5	LF Tires - 18/32 inch	LR Tires - 20/32 inch
RF Tires - 19/32 inch	RR Tires - 20/32 inch	Tire Brand - Front Left - MICHELIN
Tire Brand - Front Right - MICHELIN	Tire Brand - Rear Left - MICHELIN	Tire Brand - Rear Right - MICHELIN
Tire Model - LF - XZE2	Tire Model - LR - Xde M/S	Tire Model - RF - XZE2
Tire Model - RR - Xde M/S		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Door	Chipped	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Corrosion	-	> 12 Inches
	Right Rear Wheel	Corrosion	-	> 12 Inches
	Lift Gate	Multiple Dents/Paint Damage	-	5
	Tailgate	Rust	-	> 12 Inches
	Cargo Box Left Side Wall	Multiple Scratches Heavy	-	3
	Left Rear Wheel	Corrosion	-	> 12 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Wheel	Corrosion	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.