



Approved CR

IAA Des Moines
1000 Armstrong Dr
Branch No 536
De Soto, IA 50069
(515)823-0600/(515)823-0626
WHOLESALE ASSESSMENT ONLY

Make/Model: **2024
CHEVROLET
EQUINOX**

Bodystyle/Series: **Sport Utility
Vehicle FWD
LS**

Color: **Gray**

Mileage: **72,196
(Verified)**

Turn-in Mileage: **-**

VIN: **3GNAXHEG2RL226925**

Work Order/
Stock Number: **45623344**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G41B0135**

Vehicle Grade : **Grade 0.8**

Remarks: **-**

Announcements:

**• SALVAGE
TITLE**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	No
Engine Size:	1.5 L	Pwr Steering:	No
Roof:	-	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	- /GRAY	Rear Defroster:	No
Airbag:	-	Tilt Steering:	No
Seats:	-	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	-

Equipment

Additional Equipment:

Car Tire Size - LR 225 / 65 R 17

Car Tire Size - RR 225 / 65 R 17

Car Tire Size - RF 225 / 65 R 17

Car Tire Size - LF 225 / 65 R 17

LF Tires - 6/32 inch

LR Tires - 5/32 inch

RF Tires - 6/32 inch

RR Tires - 5/32 inch

Tire Brand - Front Left - MICHELIN

Tire Brand - Front Right - MICHELIN

Tire Brand - Rear Left - MICHELIN

Tire Brand - Rear Right - MICHELIN

Tire Model - LF - Primacy A/S

Tire Model - LR - Primacy A/S

Tire Model - RF - Primacy A/S

Tire Model - RR - Primacy A/S

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Inner Qtr Panel	Kinked	-	> 12 Inches
	Right C Pillar	Kinked	-	> 12 Inches
	Warning Light - Air Bag	On	-	Unacceptable
	Warning Light - Srs	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Rear Door	Severe Damage	-	Replacement Required
	Right Qtr Panel	Severe Damage	-	Replacement Required
	Rr Axle Assembly	Broken	-	Replacement Required
	Left Side Curtain Air Bag	Deployed	-	Replacement Required
	Right Side Curtain Air Bag	Deployed	-	Replacement Required
	Windshield	Star In Glass	-	1 To 2 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rf Seat Air Bag	Deployed	-	Replacement Required
	Right Rear Wheel	Curb Rash	-	2 To 3 Inches
	Left Qtr Panel	Scuffed	-	1 To 2 Inches
	Left Front Door	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Left Front Fender	Heavy Scratch	-	1/8 To 1/2 Inch
	Front Bumper	Chipped	-	5

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Bumper	Broken	-	Replacement Required
	Left Rear Door	Dent(S) W/No Paint Dmg	-	Pdr-1 Dent

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.