



Approved CR

IAA Des Moines
1000 Armstrong Dr
Branch No 536
De Soto, IA 50069
(515)823-0600/(515)823-0626
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD
FUSION
HYBRID**

Bodystyle/Series: **4 Door Sedan
S**

Color: **Blue**

Mileage: **49,383
(Verified)**

Turn-in Mileage: **-**

VIN: **3FA6P0UU7JR282101**

Work Order/
Stock Number: **46050983**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G10-2364V**

Vehicle Grade : **Grade 3.7**

Remarks: **-**

Announcements: **• Hail Damage**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Continuously Variable Transmission	A/C:	No
Engine:	4-Cylinder Hybrid	Cruise Control:	No
Engine Size:	2 L	Pwr Steering:	No
Roof:	-	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	- /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	No
Seats:	-	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	-

Equipment

Additional Equipment:

Car Tire Size - RR 225 / 50 R 17

Car Tire Size - RF 225 / 50 R 17

Car Tire Size - LF 225 / 50 R 17

Car Tire Size - LR 225 / 50 R 17

LF Tires - 6/32 inch

LR Tires - 6/32 inch

RF Tires - 8/32 inch

RR Tires - 6/32 inch

Tire Brand - Front Left - MICHELIN

Tire Brand - Front Right - UNIROYAL

Tire Brand - Rear Left - MICHELIN

Tire Brand - Rear Right - MICHELIN

Tire Model - RR - Energy Saver A/S

Tire Model - LF - Energy Saver A/S

Tire Model - LR - Energy Saver A/S

Tire Model - RF - Tiger Paw Touring A/S

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Lf Strut	Rust	-	Severe Damage
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Door	Dent(S) W/No Paint Dmg	-	1/2 To 1 Inch
	Hood	Chipped	-	3
	Left Rear Door	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Rear Bumper	Multiple Scratches Heavy	-	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.