



Approved
CR

IAA Portland/Gorham
9 Moodys Dr
Branch No 670
Gorham, ME 04038
(207) 839-2045/(207) 839-2701
WHOLESALE ASSESSMENT ONLY

Make/Model: **2015 FORD F-450**
Bodystyle/Series: **Crew Cab XL**
Color: **White**
Mileage: **69,662 (Verified)**
Turn-in Mileage: **-**
VIN: **1FT8W4DT1FEB46318**
Work Order/
Stock Number: **46304128**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G711334Y**
Vehicle Grade : **Grade 2.4**
Remarks: **-**
Announcements:

- ANNOUNCEMENTS:
Rust/Corrosion

Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	6.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Vinyl Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes


Equipment

Additional Equipment:

Car Tire Size - LF 225 / 70 R 19.5	Car Tire Size - LR 225 / 70 R 19.5	Car Tire Size - RR 225 / 70 R 19.5
Car Tire Size - RF 225 / 70 R 19.5	LF Tires - 10/32 inch	LR Tires - 10/32 inch
RF Tires - 10/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - CONTINENTAL
Tire Brand - Front Right - CONTINENTAL	Tire Brand - Rear Left - CONTINENTAL	Tire Brand - Rear Right - CONTINENTAL
Tire Model - RF - HDR+ - 19.5	Tire Model - LR - HDR+ - 19.5	Tire Model - LF - HDR+ - 19.5
Tire Model - RR - HDR+ - 19.5		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Metal Bumper Painted	Rust	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Steering Wheel	Worn	-	Replacement Required
	Front Metal Bumper Painted	Multiple Scratches Heavy	-	3
	Left Front Wheel	Corrosion	-	2 To 3 Inches
	Left Front Door	Multiple Scratches Heavy	-	2
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Tailgate	Dent(S) W/ Paint Dmg	-	2 To 3 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Inside Bed	Rust	-	Severe Damage
	Bedliner	Broken	-	Replacement Required
	Right Front Wheel	Curb Rash	-	9 To 10 Inches
	Tailgate Emblem	Missing	-	Replacement Required
	Right Rear Wheel	Corrosion	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.