



Approved CR

IAA Indianapolis
3302 South Harding Street
Branch No 541
Indianapolis, IN 46217
(317) 787-3202/(317)783-0586
WHOLESALE ASSESSMENT ONLY

Make/Model: **2004 INTERNATIONAL 4000**
Bodystyle/Series: **- 4200**
Color: **White**
Mileage: **43,656 (Verified)**
Turn-in Mileage: **-**
VIN: **1HTMPAFM94H655877**
Work Order/ Stock Number: **46373530**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G710336U**
Vehicle Grade : **Grade 3.3**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair Order: **-**



Drivable: Yes

Equipment

Transmission:	-	A/C:	No
Engine:	8-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	-	Pwr Steering:	Yes
Roof:	Carriage	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	Cloth/Vinyl /-	Rear Defroster:	No
Airbag:	-	Tilt Steering:	No
Seats:	Bench	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 9 / 22.5 R 12

Car Tire Size - RF 9 / 22.5 R 12

Car Tire Size - LF 9 / 22.5 R 12

Car Tire Size - LR 9 / 22.5 R 12

LF Tires - 4/32 inch

LR Tires - 10/32 inch

RF Tires - 7/32 inch

RR Tires - 8/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - GOODYEAR

Tire Model - RR - G159A

Tire Model - RF - t559 radial

Tire Model - LR - t559 radial

Tire Model - LF - t559 radial

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Stereo	Aftermarket	-	Acceptable

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Head Lamp	Faded	-	Repair Required
	Right Head Lamp	Faded	-	Repair Required
	Front Metal Bumper Painted	Rust	-	> 12 Inches
	Dash Cluster Lens	Cracked	-	Replacement Required
	Left Rear Wheel	Rust	-	Repair Required
	Right Rear Wheel	Rust	-	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.