



Approved CR

IAA Des Moines
1000 Armstrong Dr
Branch No 536
De Soto, IA 50069
(515)823-0600/(515)823-0626
WHOLESALE ASSESSMENT ONLY

Make/Model: **2011 FORD
RANGER**
Bodystyle/Series: **Extended Cab
XLT**
Color: **Blue**
Mileage: **76,515
(Verified)**
Turn-in Mileage: -
VIN: **1FTLR4FE1BPA07174**
Work Order/
Stock Number: **46304472**
Customer: GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov
Client Stock #: **G61-C6281**
Vehicle Grade : **Grade 1.9**
Remarks: -
Announcements:

- BODY

RUST
PRESENT

Certification : -
Req. Prev. Repair -
Order: -



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	No
Engine Size:	4 L	Pwr Steering:	No
Roof:	-	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	- /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	No
Seats:	-	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	-

Equipment

Additional Equipment:

Car Tire Size - LF 235 / 75 R 15	Car Tire Size - RF 235 / 75 R 15	Car Tire Size - RR 235 / 75 R 15
Car Tire Size - LR 235 / 75 R 15	LF Tires - 7/32 inch	LR Tires - 9/32 inch
RF Tires - 6/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - LF - Wrangler Trailrunner At	Tire Model - LR - Wrangler Trailrunner At	Tire Model - RF - Wrangler Trailrunner At
Tire Model - RR - Wrangler Trailrunner At		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Left Front Door	Rust	-	7 To 8 Inches
	Left Rocker Panel	Rust	-	4 To 5 Inches
	Left Front Fender	Rust	-	1 To 2 Inches
	Left Front Wheel	Corrosion	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Seat Bolster	Torn	-	> 12 Inches
	Right Fog Lamp	Faded	-	Repair Required
	Left Headlamp Mounting Panel	Chipped	-	2
	Right Front Fender	Multiple Scratches Heavy	-	2
	Right Rocker Panel	Rust	-	4 To 5 Inches
	Right Front Door	Rust	-	1 To 2 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Corrosion	-	> 12 Inches
	Right Bed Side	Multiple Scratches Heavy	-	3
	Right Rear Wheel	Corrosion	-	> 12 Inches
	Left Front Seat Cushion	Torn	-	> 12 Inches
	Tailgate	Multiple Scratches Heavy	-	10 Or More
	Rear Metal Bumper Painted	Rust	-	7 To 8 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Floor Mat	Torn	-	5 To 6 Inches
	Front Metal Bumper Painted	Multiple Scratches Heavy	-	7
	F Bumper Textured	Cracked	-	1 To 2 Inches
	Left Bed Side	Multiple Dents/Paint Damage	-	3
	Roof	Multiple Dents/Paint Damage	-	4

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.