



Approved CR

IAA Des Moines
1000 Armstrong Dr
Branch No 536
De Soto, IA 50069
(515)823-0600/(515)823-0626
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 FORD F-550 CHASSIS**
Bodystyle/Series: **Regular Cab XL**
Color: **White**
Mileage: **33,086 (Verified)**
Turn-in Mileage: **-**
VIN: **1FDAF5GT9HED73399**
Work Order/
Stock Number: **46279868**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G32-0373U**
Vehicle Grade : **Grade 2.2**
Remarks: **-**
Announcements:

- RUST ON ROOF
- CHECK ENGINE LIGHT ON
- HAIL DAMAGE

Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes


Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Diesel	Cruise Control:	No
Engine Size:	6.7 L	Pwr Steering:	No
Roof:	-	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	- /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	No

Equipment

Seats:	-	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	-
Additional Equipment:			
Car Tire Size - LF 225 / 70 R 19.5	Car Tire Size - LR 225 / 70 R 19.5	Car Tire Size - RR 225 / 70 R 19.5	
Car Tire Size - RF 225 / 70 R 19.5	LF Tires - 10/32 inch	LR Tires - 8/32 inch	
RF Tires - 11/32 inch	RR Tires - 13/32 inch	Tire Brand - Front Left - GOODYEAR	
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - CONTINENTAL	Tire Brand - Rear Right - MICHELIN	
Tire Model - RR - XDS2 (19.5)	Tire Model - RF - G647 RSS	Tire Model - LR - HSR	
Tire Model - LF - G647 RSS			

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Warning Light - Engine	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Hail Damage	-	7
	Cargo Box Right Side Wall	Peeling	-	3 To 4 Inches
	Rear Bumper	Gouged	-	2 To 3 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Seat Cushion	Torn	-	1/2 To 1 Inch
	Roof	Rust	-	> 12 Inches
	Front Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	2 To 3 Inches
	Cargo Box Left Side Wall	Dent(S) W/ Paint Dmg	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.