



Approved
CR

IAA Salt Lake City
1800 South 1100 West
Branch No 342
Ogden, UT 84401-0258
(801) 399-2818/(801) 393-2325
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 RAM 3500 CHASSIS**
Bodystyle/Series: **- TRADESMAN/SLT**
Color: **White**
Mileage: **27,322 (Verified)**
Turn-in Mileage: **-**
VIN: **3C7WRTAL7JG272913**
Work Order/
Stock Number: **46190999**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G631208V**
Vehicle Grade : **Grade 1.2**
Remarks: **-**
Announcements:

- STEERING AND SUSPENSION REPAIRS NEEDED.
- UNECONOMICAL TO REPAIR
- NEEDS NEW ENGINE

Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	6.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive

Equipment

Seat Count: -

Brakes:

Disc

Additional Equipment:

Car Tire Size - RR 235 / 70 R 17

Car Tire Size - RF 235 / 70 R 17

Car Tire Size - LF 235 / 70 R 17

Car Tire Size - LR 235 / 70 R 17

LF Tires - 13/32 inch

LR Tires - 12/32 inch

RF Tires - 13/32 inch

RR Tires - 12/32 inch

Tire Brand - Front Left - GOODYEAR

Tire Brand - Front Right - GOODYEAR

Tire Brand - Rear Left - GOODYEAR

Tire Brand - Rear Right - GOODYEAR

Tire Model - LR - Wrangler Duratrac

Tire Model - RF - Wrangler Duratrac

Tire Model - RR - Wrangler Duratrac

Tire Model - LF - Wrangler Duratrac

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Led Flashlight	Aftermarket	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Pickup Bed	Aftermarket	-	Acceptable
	Left Rear Rail	Previous Repair	-	Acceptable
	Right Rear Rail	Previous Repair	-	Acceptable

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Rust	-	9 To 10 Inches
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Left Rocker Panel	Scraped	-	7 To 8 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Door	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Left Front Wheel	Corrosion	-	> 12 Inches
	Left Front Seat Cushion	Torn	-	1/2 To 1 Inch
	Inside Bed	Rust	-	> 12 Inches
	Front Metal Bumper Painted	Multiple Scratches Heavy	-	4
	Hood	Dent(S) W/ Paint Dmg	-	6 To 7 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Door	Multiple Scratches Heavy	-	2
	Right Rocker Panel	Heavy Scratch	-	2 To 3 Inches
	Overall Vehicle	De-Identify	-	Removal Required
	Right Front Wheel	Curb Rash	-	> 12 Inches
	Right Side Panel	Rust	-	9 To 10 Inches
	Right Rear Wheel	Corrosion	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Exterior Rear Body Panel	Rust	-	> 12 Inches
	Rear Metal Bumper Painted	Rust	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.