



Approved
CR

IAA Providence
160 Amaral St
Branch No 644
Riverside, RI 02915
(401) 438-5254/(401) 438-3523
WHOLESALE ASSESSMENT ONLY

Make/Model: **2012 FORD F-750**
Bodystyle/Series: **- XL/XLT**
Color: **Black**
Mileage: **50,326 (Verified)**
Turn-in Mileage: **-**
VIN: **3FRWF7FG3CV321860**
Work Order/
Stock Number: **46369306**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**
Client Stock #: **G820139X**
Vehicle Grade : **Grade 2.0**
Remarks: **-**
Announcements:

**• ANNOUNCEMENTS:
Rust /Corrosion**

Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	-	A/C:	No
Engine:	6-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	6.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	Vinyl Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Air Brakes

Equipment


Additional Equipment:

Car Tire Size - LF 265 / 75 R 22	Car Tire Size - LR 265 / 75 R 22	Car Tire Size - RR 265 / 75 R 22
Car Tire Size - RF 265 / 75 R 22	LF Tires - 11/32 inch	LR Tires - 9/32 inch
RF Tires - 9/32 inch	RR Tires - 15/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - RR - G661 Hsa	Tire Model - RF - G661 Hsa	Tire Model - LR - G661 Hsa
Tire Model - LF - G661 Hsa		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Corner Panel	Rust	-	> 12 Inches
	Hood	Heavy Scratch	-	2 To 3 Inches
	Left Front Wheel	Corrosion	-	6 To 7 Inches
	Cargo Box Left Side Wall	Multiple Dents/Paint Damage	-	8
	Rear Metal Bumper Painted	Rust	-	> 12 Inches
	Lift Gate	Peeling	-	> 12 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Rear Wheel	Corrosion	-	> 12 Inches
	Cargo Box Right Side Wall	Multiple Scratches Light	-	2
	Right Front Wheel	Corrosion	-	9 To 10 Inches
	Right Running Board	Rust	-	7 To 8 Inches
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Cargo Box Roof	Multiple Dents/Paint Damage	-	10 Or More

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.