



Original CR

IAA Seattle
15801 110th Ave E
Branch No 327
Puyallup, WA 98374
(253)604-2300/(253)604-2390
WHOLESALE ASSESSMENT ONLY

Make/Model: **2021
HYUNDAI
SANTA FE**

Bodystyle/Series: **Sport Utility
Vehicle SE**

Color: **Silver**

Mileage: **33,274
(Verified)**

Turn-in Mileage: **-**

VIN: **5NMS14AJ1MH365460**

Work Order/
Stock Number: **46359642**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G411373Y**

Vehicle Grade : **Grade 1.1**

Remarks: **-**

Announcements:

- JUNK TITLE
- PARTS ONLY
- NOT TO BE TITLED FOR HWY USE

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	Front Wheel Drive

Equipment

Seat Count: -

Brakes:

Disc

Additional Equipment:

Car Tire Size - LF 235 / 60 R 18

Car Tire Size - LR 235 / 60 R 18

Car Tire Size - RR 235 / 60 R 18

Car Tire Size - RF 235 / 60 R 18

LF Tires - 11/32 inch

LR Tires - 12/32 inch

RF Tires - 11/32 inch

RR Tires - 12/32 inch

Tire Brand - Front Left - NOKIAN

Tire Brand - Front Right - NOKIAN

Tire Brand - Rear Left - NOKIAN

Tire Brand - Rear Right - NOKIAN

Tire Model - RR - all season

Tire Model - RF - all season

Tire Model - LR - all season

Tire Model - LF - all season

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Warning Light - Engine	On	-	Unacceptable
	Warning Light - Air Bag	On	-	Unacceptable
	Right Baffle	Kinked	-	> 12 Inches
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Airbag - Front Right	Deployed	-	Replacement Required
	Left Rear Door Molding	Heavy Scratch	-	6 To 7 Inches
	Right Fog Lamp	Missing	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Broken	-	Replacement Required
	Grille	Broken	-	Replacement Required
	Hood	Severe Damage	-	Replacement Required
	Right Head Lamp	Broken	-	Replacement Required
	Right Front Fender	Severe Damage	-	Replacement Required
	Left Front Wheel	Curb Rash	-	2 To 3 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Core Support	Broken	-	Replacement Required
	Left Rear Door	Dent(S) W/ Paint Dmg	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.