Approved CR

IAA East Bay
2780 Willow Pass Road
Branch No 332
Bay Point, CA 94565
(925) 458-7610/(925) 458-7615
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2016 FORD F-350 CHASSIS**
Bodystyle/Series:	**Extended Cab XL**
Color:	**White**
Mileage:	**44,886 (Verified)**
Turn-in Mileage:	-
VIN:	**1FD8X3H68GEC87928**
Work Order/ Stock Number:	**46440270**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G63-1062S**
Vehicle Grade :	**Grade 1.5**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Gas**	Cruise Control:	**No**
Engine Size:	**6.2 L**	Pwr Steering:	**Yes**
Roof:	**Coach**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Vinyl Interior /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**3rd**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - LF 245 / 75 R 17	Car Tire Size - LR 256 / 75 R 17	Car Tire Size - RR 256 / 75 R 17
Car Tire Size - RF 256 / 75 R 17	LF Tires - 13/32 inch	LR Tires - 11/32 inch
RF Tires - 13/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - COOPER
Tire Brand - Front Right - COOPER	Tire Brand - Rear Left - COOPER	Tire Brand - Rear Right - COOPER
Tire Model - RR - Discoverer AT3 LT	Tire Model - RF - Discoverer AT3 LT	Tire Model - LR - Discoverer AT3 LT
Tire Model - LF - Discoverer AT3 LT		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Running Board	Aftermarket	-	Acceptable
	Antenna	Aftermarket	-	Acceptable
	Roof	Previous Repair	-	Acceptable
	Right Rear Rail	Previous Repair	-	Acceptable
	Warning Light - Engine	On	-	Unacceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Right Running Board	Aftermarket	-	Acceptable
	Pickup Bed	Aftermarket	-	Acceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Rail	Previous Repair	-	Acceptable
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Wheel	Curb Rash	-	6 To 7 Inches
	Left Rear Door	Chipped	-	2
	Left Front Wheel	Curb Rash	-	2 To 3 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Seat Cushion	Torn	-	1/2 To 1 Inch
	Front Metal Bumper Painted	Multiple Scratches Heavy	-	6
	Inside Bed	Rust	-	> 12 Inches
	Gas Cap	Missing	-	Replacement Required
	Right Front Wheel	Curb Rash	-	> 12 Inches
	Right Front Door	Dent(S) W/No Paint Dmg	-	1 To 2 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Bed Side	Multiple Dents/Paint Damage	-	2
	Right Rear Wheel	Curb Rash	-	2 To 3 Inches
	Rear Metal Bumper Painted	Rust	-	> 12 Inches
	Tailgate	Multiple Scratches Heavy	-	5
	Front Valance	Misaligned	-	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.