Approved CR

IAA San Antonio-South
11275 South Zarzamora
Branch No 442
San Antonio, TX 78224
(210) 628-6770/(210) 628-6778
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2026 CHEVROLET SILVERADO 1500**
Bodystyle/Series:	**- 2WD STANDARD BED WT**
Color:	**Gray**
Mileage:	**13,623 (Verified)**
Turn-in Mileage:	-
VIN:	**1GCRAAEK7TZ194644**
Work Order/ Stock Number:	**46487689**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	-
Vehicle Grade :	**Grade 1.1**
Remarks:	-
Announcements:	• salvage
Certification :	-
Req. Prev. Repair Order:	-



Drivable: No

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**4-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**2.7 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - LF 255 / 70 R 17	Car Tire Size - LR 255 / 70 R 17	Car Tire Size - RR 255 / 70 R 17
Car Tire Size - RF 255 / 70 R 17	LF Tires - 10/32 inch	LR Tires - 8/32 inch
RF Tires - 10/32 inch	RR Tires - 9/32 inch	Tire Brand - Front Left - GENERAL
Tire Brand - Front Right - GENERAL	Tire Brand - Rear Left - GENERAL	Tire Brand - Rear Right - GENERAL
Tire Model - RR - Grabber HTS	Tire Model - RF - Grabber HTS	Tire Model - LR - Grabber HTS
Tire Model - LF - Grabber HTS		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning - Collision Avoidance	On	-	Unacceptable
	Warning - Traction Control	On	-	Unacceptable
	Warning Light - Abs	On	-	Unacceptable
	Warning Light - Air Bag	On	-	Unacceptable
	Warning Light - Brakes	On	-	Unacceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Multiple Scratches Heavy	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper Cover Upper	Chipped	-	5
	Right Rear Center Cap	Missing	-	Replacement Required
	Rear Metal Bumper Painted	Broken	-	Replacement Required
	Tailgate	Hole(S)	-	4 To 5 Inches
	Left Tail Light	Broken	-	Replacement Required
	Left Bed Side	Severe Damage	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Cab - Left	Dent(S) W/ Paint Dmg	-	5 To 6 Inches
	Left Rocker Panel	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Right Rear Wheel	Corrosion	-	> 12 Inches
	Right Rear Tire	Cut	-	Replacement Required
	Lr Axle Assembly	Broken	-	Replacement Required
	Left Rear Door	Dent(S) W/ Paint Dmg	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Windshield	Multiple Chips	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.