Approved CR

IAA Newburgh
39 Stone Castle Road
Branch No 635
Rock Tavern, NY 12575
(845) 567-6360/(845) 567-6366
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2018 RAM 2500**
Bodystyle/Series:	**Crew Cab TRADESMAN 4X4 8` BOX**
Color:	**Black**
Mileage:	**36,521 (Verified)**
Turn-in Mileage:	-
VIN:	**3C6TR5HT1JG361742**
Work Order/ Stock Number:	**46502288**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G633417V**
Vehicle Grade :	**Grade 3.0**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**5.7 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Leather Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Anti Lock Brakes**

Equipment


Additional Equipment:

Car Tire Size - RR 245 / 70 R 17	Car Tire Size - RF 245 / 70 R 17	Car Tire Size - LF 245 / 70 R 17
Car Tire Size - LR 245 / 70 R 17	LF Tires - 8/32 inch	LR Tires - 8/32 inch
RF Tires - 8/32 inch	RR Tires - 9/32 inch	Tire Brand - Front Left - ARGUS ADVANTA
Tire Brand - Front Right - ARGUS ADVANTA	Tire Brand - Rear Left - ARGUS ADVANTA	Tire Brand - Rear Right - ARGUS ADVANTA
Tire Model - LF - SVT-02	Tire Model - LR - SVT-02	Tire Model - RF - SVT-02
Tire Model - RR - SVT-02		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Left Running Board	Aftermarket	-	Acceptable
	Right Running Board	Aftermarket	-	Acceptable
	Right Side Panel	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Seat Cushion	Torn	-	1/8 To 1/2 Inch

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Dash Cluster Lens	Cracked	-	Replacement Required
	Hood	Multiple Scratches Heavy	-	4
	Overall Vehicle	De-Identify	-	Removal Required
	Left Rear Wheel	Corrosion	-	4 To 5 Inches
	Left Bed Side	Multiple Scratches Heavy	-	5
	Tailgate	Misaligned	-	Repair Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	7 To 8 Inches
	Right Rear Wheel	Corrosion	-	2 To 3 Inches
	Right Bed Side	Multiple Scratches Light	-	8
	Right Front Wheel	Corrosion	-	3 To 4 Inches
	Right Front Door	Chipped	-	3
	Right Front Fender	Multiple Scratches Light	-	5

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Chipped	-	5
	Left Front Wheel	Corrosion	-	2 To 3 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.