Approved CR

IAA Dothan
15994 Us Highway 431 N
Branch No 731
Headland, AL 36345
(334) 693-4910/(334) 693-4920
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2024 HYUNDAI ELANTRA HYBRID**
Bodystyle/Series:	**4 Door Sedan BLUE**
Color:	**Black**
Mileage:	**16,707 (Verified)**
Turn-in Mileage:	-
VIN:	**KMHLM4DJ2RU115292**
Work Order/ Stock Number:	**46517569**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G13A3713**
Vehicle Grade :	**Grade 1.9**
Remarks:	-
Announcements:	• Salvage
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	-	A/C:	**No**
Engine:	**4-Cylinder Hybrid**	Cruise Control:	**Yes**
Engine Size:	**1.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Anti Lock Brakes**

Equipment

Additional Equipment:

Car Tire Size - LF 205 / 55 R 16	Car Tire Size - LR 205 / 55 R 16	Car Tire Size - RR 205 / 55 R 16
Car Tire Size - RF 205 / 55 R 16	LF Tires - 8/32 inch	LR Tires - 9/32 inch
RF Tires - 8/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - KUMHO
Tire Brand - Front Right - KUMHO	Tire Brand - Rear Left - KUMHO	Tire Brand - Rear Right - KUMHO
Tire Model - RR - Solus TA31	Tire Model - RF - Solus TA31	Tire Model - LR - Solus TA31
Tire Model - LF - Solus TA31		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Core Support	Broken	-	Replacement Required
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Lf Mirror Cover	Bug Damage	-	Repair Required
	Left Front Fender	Dent(S) W/ Paint Dmg	-	7 To 8 Inches
	Rear Bumper Cover Upper	Multiple Scratches Heavy	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Qtr Panel	Chipped	-	2
	Right Rear Door	Chipped	-	3
	Grille	Missing	-	Replacement Required
	Front Bumper	Missing	-	Replacement Required
	Right Head Lamp	Missing	-	Replacement Required
	Left Head Lamp	Missing	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Severe Damage	-	Replacement Required
	Left Drip Rail Molding	Missing	-	Replacement Required
	Left Front Door	Dent(S) W/No Paint Dmg	-	1 To 2 Inches
	Right Front Fender	Dent(S) W/ Paint Dmg	-	3 To 4 Inches
	Radiator	Bent	-	Replacement Required
	Roof	Chipped	-	5

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.