



Approved CR

IAA Flint
3088 S. Dye Rd
Branch No 502
Flint, MI 48507
(810)720-0981/(810)732-3518
WHOLESALE ASSESSMENT ONLY

Make/Model: **2023
CHRYSLER
PACIFICA
HYBRID**

Bodystyle/Series: **Van
TOURING L**

Color: **Black**

Mileage: **50,384
(Verified)**

Turn-in Mileage: **-**

VIN: **2C4RC1L7XPR588731**

Work Order/
Stock Number: **46270277**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G413614Z**

Vehicle Grade : **Grade 1.2**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Continuously Variable Transmission	A/C:	No
Engine:	6-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Vinyl Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Power	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 235 / 65 R 17

Car Tire Size - RF 235 / 65 R 17

Car Tire Size - LF 235 / 65 R 17

Car Tire Size - LR 235 / 65 R 17

LF Tires - 5/32 inch

LR Tires - 5/32 inch

RF Tires - 5/32 inch

RR Tires - 5/32 inch

Tire Brand - Front Left - YOKOHAMA

Tire Brand - Front Right - YOKOHAMA

Tire Brand - Rear Left - YOKOHAMA

Tire Brand - Rear Right - YOKOHAMA

Tire Model - LF - Avid S34B

Tire Model - LR - Avid S34B

Tire Model - RF - Avid S34B

Tire Model - RR - Avid S34B

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right -B- Pillar	Broken	-	Replacement Required
	Warning - Tire Pressure	On	-	Unacceptable
	Warning Light - Engine	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Door	Severe Damage	-	Replacement Required
	Front Bumper	Bug Damage	-	Repair Required
	Right Front Wheel	Curb Rash	-	9 To 10 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rf Axle Assembly	Broken	-	Replacement Required
	Right Rear Door	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Right Qtr Panel	Scraped	-	2 To 3 Inches
	Right Rocker Panel Molding	Multiple Scratches Heavy	-	4
	Rear Bumper	Multiple Scratches Heavy	-	4
	Left Rear Door	Multiple Scratches Light	-	5

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Door	Multiple Scratches Heavy	-	3
	Roof	Chipped	-	3
	Right Front Tire	Cut	-	Replacement Required
	Hood	Bug Damage	-	Repair Required
	Right Front Fender	Dent(S) W/ Paint Dmg	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.