Approved
CR

IAA East Bay
2780 Willow Pass Road
Branch No 332
Bay Point, CA 94565
(925) 458-7610/(925) 458-7615
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2020 CHEVROLET TAHOE**
Bodystyle/Series:	**Sport Utility Vehicle 4WD COMMERCIAL FLEET**
Color:	**White**
Mileage:	**75,120 (Verified)**
Turn-in Mileage:	-
VIN:	**1GNSKFEC6LR111619**
Work Order/ Stock Number:	**46440242**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G62-5424W**
Vehicle Grade :	**Grade 2.0**
Remarks:	-
Announcements:	• SALVAGE STAMPED CERTIFICATE TO OBTAIN TITLE WILL BE ISSUED • REAR DOORS / WINDOWS INOPERABLE MAY BE INOPERABLE • FORMER POLICE VEHICLE • CONDITION UNKNOWN
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**5.3 L**	Pwr Steering:	**Yes**
Roof:	**Coach**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**3rd**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Disc**


Additional Equipment:

Car Tire Size - LF 265 / 70 R 17	Car Tire Size - LR 265 / 70 R 17	Car Tire Size - RR 265 / 70 R 17
Car Tire Size - RF 265 / 70 R 17	LF Tires - 7/32 inch	LR Tires - 7/32 inch
RF Tires - 7/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - IRONMAN
Tire Brand - Front Right - IRONMAN	Tire Brand - Rear Left - IRONMAN	Tire Brand - Rear Right - IRONMAN
Tire Model - RR - All Country AT2	Tire Model - RF - All Country AT2	Tire Model - LR - All Country AT2
Tire Model - LF - All Country AT2		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Drip Rail	Previous Repair	-	Acceptable
	Led Flashlight	Aftermarket	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Chipped	-	2
	Left Qtr Panel	Multiple Scratches Heavy	-	2
	Left Rear Door	Chipped	-	3
	Left Rear Wheel	Corrosion	-	7 To 8 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Door	Multiple Scratches Heavy	-	4
	Left Front Wheel	Corrosion	-	9 To 10 Inches
	Roof	Previous Repair	-	Substandard Repair
	Center Console	Missing	-	Replacement Required
	Right Rear Seat	Missing	-	Replacement Required
	Left Rear Seat	Missing	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Head Lamp	Faded	-	Repair Required
	Front Bumper	Multiple Scratches Heavy	-	4
	Right Front Fender	Chipped	-	3
	Right Front Wheel	Corrosion	-	3 To 4 Inches
	Right Rear Door	Chipped	-	3
	Right Rear Wheel	Corrosion	-	7 To 8 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hitchplate Cover	Missing	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.