



Approved CR

IAA Miami-North
20499 Stirling Road
Branch No 736
Southwest Ranch, FL 33332
(954)680-4370/(954)680-4372
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 FORD
EXPEDITION**
Bodystyle/Series: **Sport Utility
Vehicle XL**
Color: **Black**
Mileage: **75,234
(Verified)**
Turn-in Mileage: **-**
VIN: **1FMJU1GTXKEA46421**
Work Order/
Stock Number: **46365451**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G622834W**
Vehicle Grade : **Grade 4.0**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	5th	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 275 / 65 R 18	Car Tire Size - LR 275 / 65 R 18	Car Tire Size - RR 275 / 65 R 18
Car Tire Size - RF 275 / 65 R 18	LF Tires - 5/32 inch	LR Tires - 5/32 inch
RF Tires - 5/32 inch	RR Tires - 5/32 inch	Tire Brand - Front Left - HANKOOK
Tire Brand - Front Right - HANKOOK	Tire Brand - Rear Left - HANKOOK	Tire Brand - Rear Right - HANKOOK
Tire Model - RR - Dynapro HP2 (RA33)/HP2 Plus (RA33D)	Tire Model - RF - Dynapro HP2 (RA33)/HP2 Plus (RA33D)	Tire Model - LR - Dynapro HP2 (RA33)/HP2 Plus (RA33D)
Tire Model - LF - Dynapro HP2 (RA33)/HP2 Plus (RA33D)		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning - Tire Pressure	On	-	Unacceptable
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Hood	Chipped	-	5
	Cargo Box Right Roof Rail	Broken	-	Replacement Required
	Right Front Wheel	Curb Rash	-	1 To 2 Inches
	Right Rear Wheel	Curb Rash	-	1/2 To 1 Inch
	Lift Gate	Multiple Scratches Light	-	3
	Rear Bumper	Chipped	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Door	Chipped	-	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.