Approved
CR

IAA Albuquerque
4400 Broadway Blvd SE
Branch No 140
Albuquerque, NM 87105
(505) 873-2081/(505) 873-3029
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2019 CHEVROLET TAHOE**
Bodystyle/Series:	**Sport Utility Vehicle COMMERCIAL FLEET**
Color:	**White**
Mileage:	**67,433 (Verified)**
Turn-in Mileage:	-
VIN:	**1GNSKEEC1KR342808**
Work Order/ Stock Number:	**46481441**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G62-0540W**
Vehicle Grade :	**Grade 2.9**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**5.3 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**3rd**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - LF 265 / 70 R 17	Car Tire Size - LR 265 / 70 R 17	Car Tire Size - RR 265 / 70 R 17
Car Tire Size - RF 265 / 70 R 17	LF Tires - 7/32 inch	LR Tires - 12/32 inch
RF Tires - 8/32 inch	RR Tires - 11/32 inch	Tire Brand - Front Left - SUMITOMO
Tire Brand - Front Right - SUMITOMO	Tire Brand - Rear Left - PATRIOT	Tire Brand - Rear Right - PATHFINDER
Tire Model - RR - Pathfinder HT	Tire Model - RF - Encounter HT2	Tire Model - LR - Pathinder HT
Tire Model - LF - Encounter HT2		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Steering Wheel	Worn	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Seat Cushion	Cut	-	< 1/8 Inch
	Rear Bumper	Heavy Scratch	-	1/2 To 1 Inch
	Rear Bumper Tow Hook Cover	Missing	-	Replacement Required
	Right Front Door	Dent(S) W/ Paint Dmg	-	< 1/8 Inch
	Right Rear Door	Multiple Dents/Paint Damage	-	2
	Right Qtr Panel	Chipped	-	1

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Front Bumper	Broken	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.