Approved CR

IAA San Antonio-South
11275 South Zarzamora
Branch No 442
San Antonio, TX 78224
(210) 628-6770/(210) 628-6778
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2018 HYUNDAI IONIQ HYBRID**
Bodystyle/Series:	**4 Door Hatch Back BLUE**
Color:	**Silver**
Mileage:	**51,784 (Verified)**
Turn-in Mileage:	-
VIN:	**KMHC65LC5JU099385**
Work Order/ Stock Number:	**46487322**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G132707V**
Vehicle Grade :	**Grade 2.7**
Remarks:	-
Announcements:	• Hail Damage
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	-	A/C:	**No**
Engine:	**4-Cylinder Hybrid**	Cruise Control:	**Yes**
Engine Size:	**1.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - LF 195 / 65 R 15	Car Tire Size - LR 195 / 65 R 15	Car Tire Size - RR 195 / 65 R 15
Car Tire Size - RF 195 / 65 R 15	LF Tires - 12/32 inch	LR Tires - 12/32 inch
RF Tires - 12/32 inch	RR Tires - 12/32 inch	Tire Brand - Front Left - ARIZONIAN
Tire Brand - Front Right - ARIZONIAN	Tire Brand - Rear Left - ARIZONIAN	Tire Brand - Rear Right - ARIZONIAN
Tire Model - RR - Silver Edition	Tire Model - RF - Silver Edition	Tire Model - LR - Silver Edition
Tire Model - LF - Silver Edition		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Steering Wheel	Worn	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	3
	Left Head Lamp	Faded	-	Repair Required
	Right Head Lamp	Faded	-	Repair Required
	Right Front Wheel Cover	Curb Rash	-	1/2 To 1 Inch
	Right Rear Door	Scraped	-	5 To 6 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Qtr Panel	Scraped	-	6 To 7 Inches
	Right Rear Wheel Cover	Curb Rash	-	2 To 3 Inches
	Rear Bumper	Heavy Scratch	-	6 To 7 Inches
	Lf Door Handle Cap	Missing	-	Replacement Required
	Lf Mirror Cover	Peeling	-	5 To 6 Inches
	Roof	Hail Damage	-	10 Or More

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Windshield	Chipped	-	1/8 To 1/2 Inch
	Left Rear Door	Heavy Scratch	-	> 12 Inches
	Left Front Door	Heavy Scratch	-	1 To 2 Inches
	Hood	Chipped	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.