



Approved CR

IAA Las Vegas
3225 South Hollywood Blvd
Branch No 152
Las Vegas, NV 89122
(702) 565-8795/(702) 564-6553
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD
F-250**
Bodystyle/Series: **Regular Cab
XL**
Color: **White**
Mileage: **27,135
(Verified)**
Turn-in Mileage: **-**
VIN: **1FDBF2A63JEC69471**
Work Order/
Stock Number: **46338985**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G430710V**
Vehicle Grade : **Grade 1.8**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	No
Engine Size:	6.2 L	Pwr Steering:	Yes
Roof:	Carriage	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	Leather Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	5th	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Air Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 245 / 75 R 17

Car Tire Size - RF 245 / 75 R 17

Car Tire Size - LF 245 / 75 R 17

Car Tire Size - LR 245 / 75 R 17

LF Tires - 9/32 inch

LR Tires - 8/32 inch

RF Tires - 6/32 inch

RR Tires - 7/32 inch

Tire Brand - Front Left - ROADX

Tire Brand - Front Right - ROADX

Tire Brand - Rear Left - ROADX

Tire Brand - Rear Right - ROADX

Tire Model - LF - Rxquest H/T HX01

Tire Model - LR - Rxquest H/T HX01



Tire Model - RF - Rxquest H/T HX01

Tire Model - RR - Rxquest H/T HX01

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Rail	Previous Repair	-	Acceptable
	Pickup Bed	Aftermarket	-	Acceptable
	Left Rear Rail	Previous Repair	-	Acceptable
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Steering Wheel	Worn	-	Replacement Required
	Inside Bed	Multiple Scratches Heavy	-	10 Or More
	Left Front Wheel	Corrosion	-	2 To 3 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Wheel	Corrosion	-	2 To 3 Inches
	Left Bed Side	Chipped	-	3
	Tailgate	Multiple Scratches Heavy	-	8
	Front Metal Bumper Painted	Multiple Scratches Heavy	-	3
	Right Front Wheel	Corrosion	-	2 To 3 Inches
	Right Bed Side	Multiple Scratches Heavy	-	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	3 To 4 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.