Approved
CR

IAA Fontana
9951 Banana Ave
Branch No 132
Fontana, CA 92335
(909)355-9400/(909)822-9311
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2019 CHEVROLET EXPRESS 2500**
Bodystyle/Series:	**Van LS**
Color:	**White**
Mileage:	**68,729 (Verified)**
Turn-in Mileage:	-
VIN:	**1GAWGEFG4K1344623**
Work Order/ Stock Number:	**45729706**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G433314W**
Vehicle Grade :	**Grade 2.2**
Remarks:	-
Announcements:	• ENGINE MAY NEED REPAIRS OR REPLACEMENT • TOWED IN • MUST BE TOWED OUT • CONDITION UNKNOWN
Certification :	-
Req. Prev. Repair Order:	-

Drivable: No

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Flex Fuel**	Cruise Control:	**No**
Engine Size:	**6 L**	Pwr Steering:	**No**
Roof:	-	Pwr Locks:	**No**
Radio:	-	Pwr Windows	**No**
Interior - Type/Color:	- /-	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**No**

Equipment

Seats:	-	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	-

Additional Equipment:

Car Tire Size - LF 245 / 75 R 16	Car Tire Size - LR 245 / 75 R 16	Car Tire Size - RR 245 / 75 R 16
Car Tire Size - RF 245 / 75 R 16	LF Tires - 9/32 inch	LR Tires - 6/32 inch
RF Tires - 2/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - BLACKHAWK
Tire Brand - Front Right - BLACKHAWK	Tire Brand - Rear Left - BLACKHAWK	Tire Brand - Rear Right - BLACKHAWK
Tire Model - RR - Hiscend-H HT01	Tire Model - RF - Hiscend-H HT01	Tire Model - LR - Hiscend-H HT01
Tire Model - LF - Hiscend-H HT01		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning Light - Engine	On	-	Unacceptable

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Side Cargo Door	Previous Repair	-	Substd Mismatch Color
	Overall Vehicle	De-Identify	-	Removal Required
	Right Front Seat Back	Torn	-	3 To 4 Inches
	Right Front Seat Cushion	Stained	-	Permanent
	3rd Row Seat	Stained	-	Permanent

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Seat Back	Torn	-	9 To 10 Inches
	Left Front Seat Back	Torn	-	4 To 5 Inches
	Left Front Seat Cushion	Torn	-	9 To 10 Inches
	Right Front Tire	Worn	-	Replacement Required
	Right Rear Seat Cushion	Stained	-	Permanent
	Left Front Door	Dent(S) W/ Paint Dmg	-	3 To 4 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Lift Gate Trim Panel	Broken	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.