Approved CR

IAA Honolulu
91-445A Komohana St
Branch No 114
Kapolei, HI 96707
(808) 682-2858/(808) 682-3988
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2016 CHEVROLET COLORADO**
Bodystyle/Series:	**Extended Cab WT**
Color:	**White**
Mileage:	**16,188 (Verified)**
Turn-in Mileage:	-
VIN:	**1GCHSBEA8G1311853**
Work Order/ Stock Number:	**46509783**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G43B5165**
Vehicle Grade :	**Grade 2.9**
Remarks:	-
Announcements:	• REPAIR HISTORY NOT AVAILABLE. CONDITION UNKNOWN • PARTS MAY BE MISSING • NON GSA OWNED VEHICLE • REPAIRS MAY BE NEEDED
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**4-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**2.5 L**	Pwr Steering:	**Yes**

Equipment

Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Memory**	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	**Hydraulic Brakes**


Additional Equipment:

Car Tire Size - RR 265 / 70 R 16	Car Tire Size - RF 265 / 70 R 16	Car Tire Size - LF 265 / 70 R 16
Car Tire Size - LR 265 / 70 R 16	LF Tires - 9/32 inch	LR Tires - 10/32 inch
RF Tires - 10/32 inch	RR Tires - 9/32 inch	Tire Brand - Front Left - SAILUN
Tire Brand - Front Right - SAILUN	Tire Brand - Rear Left - SAILUN	Tire Brand - Rear Right - SAILUN
Tire Model - LF - Terramax HLT	Tire Model - LR - Terramax HLT	Tire Model - RF - Terramax HLT
Tire Model - RR - Terramax HLT		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	9 To 10 Inches
	Tailgate	Multiple Dents/Paint Damage	-	6
	Right Rear Wheel	Curb Rash	-	2 To 3 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Bed Side	Multiple Scratches Heavy	-	2
	Right Front Wheel	Curb Rash	-	1 To 2 Inches
	Front Bumper	Chipped	-	4
	Left Front Wheel	Corrosion	-	> 12 Inches
	Roof	Chipped	-	2
	Right Drip Rail	Chipped	-	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Inside Bed	Multiple Scratches Heavy	-	10 Or More
	Left Head Lamp	Faded	-	Repair Required
	Left Rocker Panel	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Hood	Chipped	-	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.