



Approved CR

Rawls Auto Auction Inc.
2818 Pond Branch Rd.
Leesville, SC 29070
(803) 859-5111/(803) 859-0517
wendyc@rawlsautoauction.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 BLUE
BIRD BUS**

Bodystyle/Series: **2 Door
Vehicle -**

Color: **WHITE**

Mileage: **117,520
(Verified, 6
digits)**

Turn-in Mileage: **-**

VIN: **1BABNBPA1HF329359**

Work Order/
Stock Number: **000381478**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G320160S**

Vehicle Grade : **Grade 1.0**

Remarks: **-**

Announcements: **• UER / INOP**

Certification : **Not Certified**

Req. Prev. Repair **-**

Order: **-**



Drivable: No

UniBody/Frame Damage: NO As Is 100K Miles: YES

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Diesel Turbo	Cruise Control:	No
Engine Size:	6.7 L	Pwr Steering:	No
Roof:	Hard Top	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	Vinyl Interior /GRAY	Rear Defroster:	No
Airbag:	-	Tilt Steering:	No
Seats:	-	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	-

Equipment



Additional Equipment:

3rd Row Seat	5th Row Seat	Car Tire Size - RR tire size 11R22.5
Car Tire Size - RF tire size 11R22.5	Car Tire Size - LR tire size 11R22.5	Car Tire Size - LF tire size 11R22.5
Cylinders - 6	Dual Rear Wheels	Foul Odor
LF Tires - 4/32 inch	LR Tires - 16/32 inch	Master Key - 2key(s)
Motor Fuel Type - Diesel	RF Tires - 5/32 inch	Rear View Mirror
Seat Trim - Vinyl	Tire Brand - Front Left - LF tire mfg Toyo	Tire Brand - Front Right - RF tire mfg Toyo
Tire Brand - Rear Left - LR tire mfg Firestone	Tire Brand - Rear Right - RR tire mfg Other	Transmission - Automatic Transmission
Turbocharged	Two-Wheel Drive	Wheels Front Left - Steel
Wheels Front Right - Steel	Wheels Rear Left - Steel	Wheels Rear Right - Steel

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Door Panels	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	Extra Photo 6	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Extra Photo 7	Photo Only	Estimate Only	Unknown
	Extra Photo 8	Photo Only	Estimate Only	Unknown
	Extra Photo 9	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Qtr Panel	Dent(S) W/ Paint Dmg	Repair	> 12 Inches
	Left Rear Seat	Torn	Replace	> 12 Inches
	R Cab Corner Panel	Dent(S) W/ Paint Dmg	Repair	> 12 Inches
	Rear Bumper	Multiple Scratches Heavy	Repair	10 Or More

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Rear Door	Dent(S) W/ Paint Dmg	Repair	> 12 Inches
	Right Rear Seat	Torn	Replace	> 12 Inches
	3rd Row Seat	Torn	Replace	> 12 Inches
	4th Row Seat	Torn	Replace	> 12 Inches
	5th Row Seat	Torn	Replace	> 12 Inches
[no photo]	Overall Vehicle	Multiple Scratches Light	Wet Sand	10 Or More
	Front Bumper	Multiple Scratches Heavy	Repair	10 Or More

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.