Approved CR

IAA High Desert
11385 G Avenue
Branch No 133
Hesperia, CA 92345
(760)949-8404/(760)949-0400
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2018 RAM 1500**
Bodystyle/Series:	**Crew Cab TRADESMAN 4X4 5`7 BOX**
Color:	**White**
Mileage:	**44,048 (Verified)**
Turn-in Mileage:	-
VIN:	**1C6RR7KG1JS300529**
Work Order/ Stock Number:	**46427397**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G622772V**
Vehicle Grade :	**Grade 1.7**
Remarks:	-
Announcements:	• WARNING INDICATOR LIGHT ON (SEE IAA CONDITION REPORT FOR DETAILS)
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Flex Fuel**	Cruise Control:	**No**
Engine Size:	**3.6 L**	Pwr Steering:	**No**
Roof:	-	Pwr Locks:	**No**
Radio:	-	Pwr Windows	**No**
Interior - Type/Color:	- /-	Rear Defroster:	**No**
Airbag:	-	Tilt Steering:	**No**
Seats:	-	Drive Type:	**4-Wheel Drive**

Equipment

Seat Count: -

Brakes: -

Additional Equipment:

Car Tire Size - LF 265 / 70 R 17	Car Tire Size - LR 265 / 70 R 17	Car Tire Size - RR 265 / 70 R 17
Car Tire Size - RF 265 / 70 R 17	LF Tires - 10/32 inch	LR Tires - 9/32 inch
RF Tires - 9/32 inch	RR Tires - 12/32 inch	Tire Brand - Front Left - GENERAL
Tire Brand - Front Right - GENERAL	Tire Brand - Rear Left - GENERAL	Tire Brand - Rear Right - GENERAL
Tire Model - RR - Grabber A/TX	Tire Model - RF - Grabber A/TX	Tire Model - LR - Grabber A/TX
Tire Model - LF - Grabber A/TX		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning - Tire Pressure	On	-	Unacceptable
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Inside Bed	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Front Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Right Rocker Panel	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Right Front Door	Heavy Scratch	-	2 To 3 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Right Bed Side	Dent(S) W/ Paint Dmg	-	3 To 4 Inches
	Tailgate	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Left Bed Side	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Left Rocker Panel	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Left Rear Door	Chipped	-	1

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Center Cap	Missing	-	Replacement Required
	Left Head Lamp	Faded	-	Repair Required
	Right Rear Seat Cushion	Torn	-	1/8 To 1/2 Inch
	Left Front Seat Cushion	Torn	-	> 12 Inches
	Steering Wheel	Worn	-	Replacement Required
	Tailgate Molding	Broken	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.