



Approved CR

IAA Tulsa
5311 W 46th Street S
Branch No 436
Tulsa, OK 74107
(918) 445-4691/(918) 445-4905
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 RAM
2500
Crew Cab**
Bodystyle/Series: **TRADESMAN
4X4 8' BOX**
Color: **White**
Mileage: **55,620
(Verified)**
Turn-in Mileage: -
VIN: **3C6TR5HT3JG375223**
Work Order/
Stock Number: **46230406**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: -
Vehicle Grade : **Grade 2.5**
Remarks: -
Announcements:

- Warning Light; Active Codes see IAA Condition Report

Certification : -
Req. Prev. Repair -
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	5.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 245 / 75 R 17	Car Tire Size - RF 245 / 75 R 17	Car Tire Size - LF 245 / 75 R 17
Car Tire Size - LR 245 / 75 R 17	LF Tires - 4/32 inch	LR Tires - 4/32 inch
RF Tires - 4/32 inch	RR Tires - 5/32 inch	Tire Brand - Front Left - COOPER
Tire Brand - Front Right - COOPER	Tire Brand - Rear Left - COOPER	Tire Brand - Rear Right - COOPER
Tire Model - LR - Discoverer AT3 LT	Tire Model - LF - Discoverer AT3 LT	Tire Model - RR - Discoverer AT3 LT
Tire Model - RF - Discoverer AT3 LT		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Trailer Hitch	Aftermarket	-	Acceptable
	Warning - Tire Pressure	On	-	Unacceptable
	Warning Light - Air Bag	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Chipped	-	8
	Right Rocker Panel	Heavy Scratch	-	1/2 To 1 Inch

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Corrosion	-	2 To 3 Inches
	Right Rear Wheel	Corrosion	-	6 To 7 Inches
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	2 To 3 Inches
	Tailgate	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Tailgate Protective Cap	Missing	-	Replacement Required
	Left Bed Side	Chipped	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Wheel	Corrosion	-	1/2 To 1 Inch
	Roof	Chipped	-	3
	Inside Bed	Multiple Scratches Heavy	-	10 Or More
	Left Front Door	Multiple Dents/Paint Damage	-	3
	Left Front Fender	Chipped	-	1
	Left Rocker Panel	Multiple Scratches Heavy	-	4

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Chipped	-	4

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.