



Approved CR

Akron Auto Auction
2471 Ley Drive
Akron, OH 44319
3304365819/(330) 773-3921
lbeth@akronautoauction.com
WHOLESALE ASSESSMENT ONLY

Make/Model: 2023
HYUNDAI
ELANTRA
HYBRID
4 Door Sedan
Bodystyle/Series: BLUE 4D
SEDAN AT
Color: GRAY
Mileage: 51,612
(Verified, 6
digits)
Turn-in Mileage: -
VIN: KMHLM4AJXPU086142
Work Order/
Stock Number: 000931100
Customer: GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov
Client Stock #: G13A0735
Vehicle Grade : Grade 1.1
AutoGrade : 1.1 - Rough
Remarks: only one
government
plate. `A`
plate is
missing. tow:
severe front
collision
d/amage.
front end
pushe
Announcements: • Total Salvage
Certification : Not Certified
Req. Prev. Repair -
Order:



Drivable: No

UniBody/Frame Damage: YES As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	1.6 L	Pwr Steering:	Yes

Equipment

Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Power Brakes
Additional Equipment:			
ABS Brakes	Air Conditioning	Automatic Headlights	
Blind Spot Monitor	Bluetooth Connection	Brake Assist System	
Car Tire Size - LF tire size P205/55HR16	Car Tire Size - RR tire size P205/55HR16	Car Tire Size - RF tire size P205/55HR16	
Car Tire Size - LR tire size P205/55HR16	Child Safety Locks	Collision Avoidance	
Cruise Control	Cylinders - 4	Daytime Running Lights	
Driver Air Bag	Empty Weight - 2965 lb	Engine Immobilizer	
Floor Mats	Front Wheel Drive	Front Wheel Drive	
HD Radio	Heated Front Seat(s)	Heated Mirrors	
Independent Climate Control	Intermittent Wipers	Keyless Entry	
Keyless Start	LF Tires - 3/32 inch	LR Tires - 5/32 inch	
Lane Departure System	MP3 Radio	Master Key - 1key(s)	
Motor Fuel Type - Other	Pass. Air Bag	Power Brakes	
Power Lock	Power Mirrors	Power Steering	
Power Trunk/Liftgate	Power Windows	RF Tires - 3/32 inch	
RR Tires - 5/32 inch	Rear Defrost	Remote Trunk Release	
Reverse Camera	Seat Trim - Cloth	Security System	
Side Airbags - Front	Spare Tire	Steering Wheel Audio Control	
Stereo - AM/FM Radio	Telematics	Tilt Steering Wheel	
Tilt Wheel	Tire Pressure Monitor System	Traction Control	
Transmission - Automatic Transmission	Trip Computer	Wheels Front Left - Aluminium	
Wheels Front Right - Aluminium	Wheels Rear Left - Aluminium	Wheels Rear Right - Aluminium	

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Steering Wheel	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Air Bags	Deployed	Replace	Replacement Required
	Core Support	Broken	Replace	Replacement Required
	Grille	Missing	Replace	Replacement Required
	Left A Pillar	Cut	Repair	1 To 2 Inches
	Left A Pillar	Kinked	Repair	7 To 8 Inches
	Left Front Tire	Worn	Replace	Replacement Required
	Right Head Lamp	Missing	Replace	Replacement Required
	Radiator	Broken	Replace	Replacement Required
	Rear Bumper	Chipped	Touch Up	2
	Right A Pillar	Chipped	Touch Up	2
	Right Front Door	Chipped	Touch Up	2
	Right Front Fender	Multiple Dents/Paint Damage	Repair	5

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Tire	Worn	Replace	Replacement Required
	Warning Light - Engine	On	Report	Unacceptable
	Windshield	Broken	Replace	Replacement Required
[no photo]	A/C Condensor	Broken	Replace	Replacement Required
[no photo]	Front Bumper Reinforcement	Bent	Replace	6 To 7 Inches
[no photo]	Front Bumper	Broken	Replace	Replacement Required
[no photo]	Hood	Severe Damage	Replace	Replacement Required
[no photo]	Fluid Level Coolant	Low Fluid	Repair	Unacceptable

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.