



Approved CR

IAA Birmingham
1600 Highway 150
Branch No 727
Bessemer, AL 35022
(205) 426-2300/(205) 428-5332
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020 FORD
F-350**

Bodystyle/Series: **Extended Cab
XL**

Color: **White**

Mileage: **122,853
(Verified)**

Turn-in Mileage: **-**

VIN: **1FD8X3B65LED99279**

Work Order/
Stock Number: **46371175**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G631724X**

Vehicle Grade : **Grade 3.3**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Leather Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 245 / 75 R 17

Car Tire Size - RF 245 / 75 R 17

Car Tire Size - LF 245 / 75 R 17

Car Tire Size - LR 245 / 75 R 17

LF Tires - 11/32 inch

LR Tires - 11/32 inch

RF Tires - 10/32 inch

RR Tires - 9/32 inch

Tire Brand - Front Left - ARROYO

Tire Brand - Front Right - ARROYO

Tire Brand - Rear Left - ARROYO

Tire Brand - Rear Right - ARROYO

Tire Model - RR - Eco Pro H/T


Tire Model - RF - Eco Pro H/T

Tire Model - LR - Eco Pro H/T

Tire Model - LF - Eco Pro H/T

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Hood	Chipped	-	10 Or More

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Center Cap	Missing	-	Replacement Required
	Rear Metal Bumper Painted	Peeling	-	> 12 Inches
	Right Rear Door	Dent(S) W/ Paint Dmg	-	3 To 4 Inches
	Steering Wheel	Worn	-	Replacement Required
	Right Rear Center Cap	Missing	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.