



Approved
CR

IAA Salt Lake City
1800 South 1100 West
Branch No 342
Ogden, UT 84401-0258
(801) 399-2818/(801) 393-2325
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017
CHEVROLET
COLORADO**

Bodystyle/Series: **Extended Cab
WT**

Color: **White**

Mileage: **36,969 (Verified)**

Turn-in Mileage: **-**

VIN: **1GCHTBEA2H1243953**

Work Order/
Stock Number: **46087412**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G610310U**

Vehicle Grade : **Grade 3.3**

Remarks: **-**

Announcements:

**• HOLE IN ROOF
FROM
AFTERMARKET
ANTENNA**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Power - Driver Only	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 265 / 70 R 16	Car Tire Size - RF 265 / 70 R 16	Car Tire Size - LF 265 / 70 R 16
Car Tire Size - LR 265 / 70 R 16	LF Tires - 7/32 inch	LR Tires - 5/32 inch
RF Tires - 9/32 inch	RR Tires - 5/32 inch	Tire Brand - Front Left - COOPER
Tire Brand - Front Right - COOPER	Tire Brand - Rear Left - NEXEN	Tire Brand - Rear Right - NEXEN
Tire Model - LF - Discoverer Road + Trail At	Tire Model - LR - Roadian Atx	Tire Model - RF - Discoverer Road + Trail At
Tire Model - RR - Roadian Atx		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Roof	Previous Repair	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Head Lamp	Faded	-	Repair Required
	Right Front Wheel	Corrosion	-	> 12 Inches
	Right Qtr Panel Extension	Misaligned	-	Repair Required
	Right Rear Wheel	Corrosion	-	7 To 8 Inches
	Tailgate	Light Scratch	-	1/2 To 1 Inch
	Left Bed Side	Multiple Dents/Paint Damage	-	3

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Rear Wheel	Curb Rash	-	1 To 2 Inches
	Left Front Wheel	Corrosion	-	2 To 3 Inches
	Front Bumper	Multiple Scratches Heavy	-	7
	Right Head Lamp	Faded	-	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.