



Approved
CR

IAA Tidewater
211 Production Drive
Branch No 725
Yorktown, VA 23693
(757) 595-8493/(757) 595-8691
WHOLESALE ASSESSMENT ONLY

Make/Model: **2009 DODGE DAKOTA**
Bodystyle/Series: **Crew Cab**
BIGHORN/LONESTAR
Color: **White**
Mileage: **57,429 (Verified)**
Turn-in Mileage: **-**
VIN: **1D3HE38P19S744545**
Work Order/
Stock Number: **46368422**
Customer: **GSA Fleet Vehicle Sales**
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov
Client Stock #: **G41A6299**
Vehicle Grade : **Grade 2.2**
Remarks: **-**
Announcements:

- please check OBDII report on IAA site. Rust CONSOLIDATED
- Warning indicator on

Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	4.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	5th	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 245 / 70 R 16

Car Tire Size - LR 245 / 70 R 16

Car Tire Size - RR 245 / 70 R 16

Car Tire Size - RF 245 / 70 R 16

LF Tires - 7/32 inch

LR Tires - 8/32 inch

RF Tires - 9/32 inch

RR Tires - 9/32 inch

Tire Brand - Front Left - GREEN
MAX

Tire Brand - Front Right - GREEN MAX

Tire Brand - Rear Left - HANKOOK

Tire Brand - Rear Right - HANKOOK

Tire Model - RR - Optimum Sport HP

Tire Model - RF - Dynapro HT RH12
(P-Metric)


Tire Model - LR - Optimum Sport HP

Tire Model - LF - Dynapro HT RH12
(P-Metric)

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning Light - Engine	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Tail Light	Cracked	-	Replacement Required
	Left Front Seat Cushion	Torn	-	3 To 4 Inches
	Left Front Wheel	Curb Rash	-	1 To 2 Inches
	Left Front Door	Multiple Scratches Heavy	-	2
	Left Rear Wheel	Curb Rash	-	2 To 3 Inches
	Left Bed Side	Multiple Scratches Heavy	-	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Tailgate	Dent(S) W/ Paint Dmg	-	3 To 4 Inches
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Right Rear Wheel	Curb Rash	-	3 To 4 Inches
	Right Bed Side	Dent(S) W/ Paint Dmg	-	3 To 4 Inches
	Right Front Wheel	Curb Rash	-	7 To 8 Inches
	Right Front Fender	Dent(S) W/No Paint Dmg	-	3 To 4 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Head Lamp	Faded	-	Repair Required
	Left Head Lamp	Faded	-	Repair Required
	Front Bumper	Multiple Scratches Heavy	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.