



Approved
CR

IAA Syracuse
8459 Brewerton Road
Branch No 628
Cicero, NY 13039
(315) 699-2622/(315) 699-5481
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 CHEVROLET
SILVERADO 2500HD**
Bodystyle/Series: **Crew Cab WT**
Color: **Silver**
Mileage: **85,295 (Verified)**
Turn-in Mileage: **-**
VIN: **1GC1KUEGXJF255703**
Work Order/
Stock Number: **46383365**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**
Client Stock #: **G633789W**
Vehicle Grade : **Grade 2.2**
Remarks: **-**
Announcements: **• ANNOUNCEMENTS:**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Leather Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 245 / 75 R 17	Car Tire Size - RF 245 / 75 R 17	Car Tire Size - LF 245 / 75 R 17
Car Tire Size - LR 245 / 75 R 17	LF Tires - 8/32 inch	LR Tires - 10/32 inch
RF Tires - 8/32 inch	RR Tires - 11/32 inch	Tire Brand - Front Left - MILESTAR
Tire Brand - Front Right - MILESTAR	Tire Brand - Rear Left - KELLY	Tire Brand - Rear Right - KELLY
Tire Model - LR - safari at	Tire Model - RF - Patagonia A/T R	Tire Model - RR - safari at
Tire Model - LF - Patagonia A/T R		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Tailgate Molding	Broken	-	Replacement Required
	Left Bed Side	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Cab - Left	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Rear Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	> 12 Inches
	Right Bed Side	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Hood	Dent(S) W/ Paint Dmg	-	4 To 5 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	9 To 10 Inches
	Right Front Fender	Heavy Scratch	-	1/2 To 1 Inch
	Tailgate	Chipped	-	3
	Right Front Seat Cushion	Torn	-	1/2 To 1 Inch
	Left Front Seat Cushion	Torn	-	1/2 To 1 Inch
	Right Drip Rail	Heavy Scratch	-	< 1/8 Inch

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Inside Bed	Dent(S) W/ Paint Dmg	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.