Approved CR

IAA Sacramento West
6734 Midway Rd
Branch No 120
Dixon, CA 95620
(707) 640-1240
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2024 CHEVROLET SILVERADO 2500HD**
Bodystyle/Series:	**Double Cab Truck 4WD LONG BED WORK TRUCK**
Color:	**White**
Mileage:	**91,768 (Verified)**
Turn-in Mileage:	-
VIN:	**1GC5YLE75RF283026**
Work Order/ Stock Number:	**46413736**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G63A1991**
Vehicle Grade :	**Grade 3.6**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**6.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**3rd**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - RR 245 / 75 R 17	Car Tire Size - RF 245 / 75 R 17	Car Tire Size - LF 245 / 75 R 17
Car Tire Size - LR 245 / 75 R 17	LF Tires - 7/32 inch	LR Tires - 8/32 inch
RF Tires - 7/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - DEAN
Tire Brand - Front Right - DEAN	Tire Brand - Rear Left - DEAN	Tire Brand - Rear Right - DEAN
Tire Model - LF - Back Country MT-3	Tire Model - LR - Back Country MT-3	Tire Model - RF - Back Country MT-3
Tire Model - RR - Back Country MT-3		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Inside Bed	Heavy Scratch	-	> 12 Inches
	Battery	Missing	-	Replacement Required
	Tailgate	Multiple Dents/Paint Damage	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.