Approved CR

IAA Fontana
9951 Banana Ave
Branch No 132
Fontana, CA 92335
(909)355-9400/(909)822-9311
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2026 NISSAN PATHFINDER**
Bodystyle/Series:	**Sport Utility Vehicle S**
Color:	**Black**
Mileage:	**1,357 (Verified)**
Turn-in Mileage:	-
VIN:	**5N1DR3AE3TC210920**
Work Order/ Stock Number:	**45402425**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G61C6168**
Vehicle Grade :	**Grade 0.5**
Remarks:	-
Announcements:	• PARTS ONLY • NOT TO BE TITLED FOR HWY USE • JUNK TITLE
Certification :	-
Req. Prev. Repair Order:	-

Drivable: No

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Gas**	Cruise Control:	**No**
Engine Size:	**3.5 L**	Pwr Steering:	**No**
Roof:	-	Pwr Locks:	**No**
Radio:	-	Pwr Windows	**No**
Interior - Type/Color:	- /-	Rear Defroster:	**No**
Airbag:	-	Tilt Steering:	**No**
Seats:	-	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	-

Equipment

Additional Equipment:

Car Tire Size - LF 255 / 60 R 18	Car Tire Size - LR 255 / 60 R 18	Car Tire Size - RR 255 / 60 R 18
Car Tire Size - RF 255 / 60 R 18	LF Tires - 8/32 inch	LR Tires - 8/32 inch
RF Tires - 8/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - HANKOOK
Tire Brand - Front Right - HANKOOK	Tire Brand - Rear Left - HANKOOK	Tire Brand - Rear Right - HANKOOK
Tire Model - RR - Dynapro HP2 (RA33)/HP2 Plus (RA33D)	Tire Model - RF - Dynapro HP2 (RA33)/HP2 Plus (RA33D)	Tire Model - LR - Dynapro HP2 (RA33)/HP2 Plus (RA33D)
Tire Model - LF - Dynapro HP2 (RA33)/HP2 Plus (RA33D)		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Front Bumper	Missing	-	Replacement Required
	Grille	Missing	-	Replacement Required
	Left Head Lamp	Missing	-	Replacement Required
	Right Head Lamp	Missing	-	Replacement Required
	Radiator	Bent	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Missing	-	Replacement Required
	Right Front Door	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Lf Fender Cladding	Missing	-	Replacement Required
	Left Front Wheel	Curb Rash	-	1/2 To 1 Inch
	Roof	Chipped	-	2
	Airbag - Front Left	Deployed	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Curtain Air Bag	Deployed	-	Replacement Required
	Right Side Curtain Air Bag	Deployed	-	Replacement Required
	Left Knee Airbag	Deployed	-	Replacement Required
	Front Bumper Reinforcement	Bent	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.