



Approved CR

IAA Birmingham
1600 Highway 150
Branch No 727
Bessemer, AL 35022
(205) 426-2300/(205) 428-5332
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020 RAM
2500**
Bodystyle/Series: **Crew Cab
TRADESMAN
4X4 8' BOX**
Color: **Black**
Mileage: **107,966
(Verified)**
Turn-in Mileage: **-**
VIN: **3C6UR5HJ8LG242138**
Work Order/
Stock Number: **46416826**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G631717U**
Vehicle Grade : **Grade 3.2**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.4 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RF 248 / 70 R 17

Car Tire Size - LF 248 / 70 R 17

Car Tire Size - RR 248 / 70 R 17

Car Tire Size - LR 248 / 70 R 17

LF Tires - 9/32 inch

LR Tires - 4/32 inch

RF Tires - 8/32 inch

RR Tires - 4/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE

Tire Model - LF - Transforce HT

Tire Model - LR - Transforce HT

Tire Model - RF - Transforce HT

Tire Model - RR - Transforce HT

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Warning Light - Engine	On	-	Unacceptable
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Running Board	Aftermarket	-	Acceptable
	Right Running Board	Aftermarket	-	Acceptable
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Wheel	Corrosion	-	1/2 To 1 Inch
	Right Front Wheel	Corrosion	-	2 To 3 Inches
	Right Rear Wheel	Corrosion	-	1/2 To 1 Inch
	Right Rear Center Cap	Missing	-	Replacement Required
	Tailgate	Multiple Dents/Paint Damage	-	5

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Tailgate Protective Cap	Missing	-	Replacement Required
	Rear Metal Bumper Painted	Chipped	-	3
	Left Rear Wheel	Corrosion	-	2 To 3 Inches
	Front Metal Bumper Painted	Chipped	-	10 Or More

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.