



Approved CR

IAA Fort Wayne
4300 Oxford St.
Branch No 547
Fort Wayne, IN 46809
(260) 261-0126/(260) 261-0127
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020 FORD
TRANSIT
CONNECT**

Bodystyle/Series: **Wagon XL
PASSENGER**

Color: **Blue**

Mileage: **114,939
(Verified)**

Turn-in Mileage: **-**

VIN: **NM0GE9E27L1456040**

Work Order/
Stock Number: **46361834**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G414654W**

Vehicle Grade : **Grade 4.1**

Remarks: **-**

Announcements:

- LEFT DRIP
RAIL
MOLDING
MISSING

Certification : **-**

Req. Prev. Repair **-**

Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2 L	Pwr Steering:	No
Roof:	Coach	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Drum

Equipment

Additional Equipment:

Car Tire Size - LF 215 / 55 R 16	Car Tire Size - LR 215 / 55 R 16	Car Tire Size - RR 215 / 55 R 16
Car Tire Size - RF 215 / 55 R 16	LF Tires - 5/32 inch	LR Tires - 5/32 inch
RF Tires - 5/32 inch	RR Tires - 5/32 inch	Tire Brand - Front Left - CONTINENTAL
Tire Brand - Front Right - CONTINENTAL	Tire Brand - Rear Left - CONTINENTAL	Tire Brand - Rear Right - CONTINENTAL
Tire Model - RR - Procontact TX	Tire Model - RF - Procontact TX	Tire Model - LR - Procontact TX
Tire Model - LF - Procontact TX		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Drip Rail Molding	Missing	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	R Bumper Textured	Dent(S) W/No Paint Dmg	-	2 To 3 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.