



Approved CR

IAA Buffalo
366 Vulcan Street
Branch No 624
Buffalo, NY 14204
(716) 874-9890/(716) 874-9605
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020
HYUNDAI
IONIQ
HYBRID**

Bodystyle/Series: **4 Door Hatch
Back BLUE**

Color: **White**

Mileage: **64,632
(Verified)**

Turn-in Mileage: **-**

VIN: **KMHC65LC3LU220031**

Work Order/
Stock Number: **46362084**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G131892X**

Vehicle Grade : **Grade 2.2**

Remarks: **-**

Announcements:

**• Announcement:
Salvage Title**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	-	A/C:	No
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	1.6 L	Pwr Steering:	Yes
Roof:	Carriage	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /-	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 195 / 65 R 15

Car Tire Size - RF 195 / 65 R 15

Car Tire Size - LF 195 / 65 R 15

Car Tire Size - LR 195 / 65 R 15

LF Tires - 7/32 inch

LR Tires - 7/32 inch

RF Tires - 7/32 inch

RR Tires - 7/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE

Tire Model - LF - Affinity Touring

Tire Model - LR - Affinity Touring

Tire Model - RF - Affinity Touring

Tire Model - RR - Affinity Touring

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Warning Light - Engine	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Missing	-	Replacement Required
	Grille	Missing	-	Replacement Required
	Left Head Lamp	Missing	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Head Lamp	Missing	-	Replacement Required
	Front Bumper Reinforcement	Missing	-	Replacement Required
	Right Front Fender	Dent(S) W/No Paint Dmg	-	1 To 2 Inches
	Right Front Fender Liner	Missing	-	Replacement Required
	Right Front Wheel Cover	Curb Rash	-	5 To 6 Inches
	Right Rear Wheel Cover	Curb Rash	-	4 To 5 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Chipped	-	3
	Left Rear Door	Heavy Scratch	-	1/2 To 1 Inch
	Left Qtr Panel	Light Scratch	-	1/2 To 1 Inch
	Deck Lid	Chipped	-	4
	Left Front Fender Liner	Missing	-	Replacement Required
	Left Drip Rail	Chipped	-	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Lf Mirror Cover	Chipped	-	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.