



Approved
CR

IAA Kansas City
2663 S 88th Street
Branch No 527
Kansas City, KS 66111
(913) 422-9303/(913) 422-7421
WHOLESALE ASSESSMENT ONLY

Make/Model: **2025 CHRYSLER VOYAGER**
Bodystyle/Series: **Van LX**
Color: **Blue**
Mileage: **33,492 (Verified)**
Turn-in Mileage: **-**
VIN: **2C4RC1CG9SR583870**
Work Order/
Stock Number: **46306429**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**
Client Stock #: **G41C0094**
Vehicle Grade : **Grade 1.1**
Remarks: **-**
Announcements:

- HAIL DAMAGE
- UNECONOMICAL TO REPAIR
- FRONT END COLLISION

Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 235 / 65 R 17

Car Tire Size - LR 235 / 65 R 17

Car Tire Size - RR 235 / 65 R 17

Car Tire Size - RF 235 / 65 R 17

LF Tires - 7/32 inch

LR Tires - 9/32 inch

RF Tires - 7/32 inch

RR Tires - 9/32 inch

Tire Brand - Front Left - YOKOHAMA

Tire Brand - Front Right - YOKOHAMA

Tire Brand - Rear Left - YOKOHAMA

Tire Brand - Rear Right - YOKOHAMA

Tire Model - RR - avid s34

Tire Model - RF - avid s34

Tire Model - LR - avid s34

Tire Model - LF - avid s34

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Left Rear Wheel Housing	Broken	-	Replacement Required

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Door	Scraped	-	> 12 Inches
	Right Front Wheel	Curb Rash	-	7 To 8 Inches
	Right Qtr Panel	Dent(S) W/ Paint Dmg	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Scraped	-	> 12 Inches
	Right Rear Wheel	Curb Rash	-	> 12 Inches
	Rear Bumper Center Molding	Missing	-	Replacement Required
	Lift Gate	Dent(S) W/ Paint Dmg	-	2 To 3 Inches
	Left Qtr Panel	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Left Rear Door	Scraped	-	9 To 10 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Wheel	Curb Rash	-	9 To 10 Inches
	Roof	Hail Damage	-	10 Or More
	Front Bumper	Broken	-	Replacement Required
	Right Head Lamp	Broken	-	Replacement Required
	Hood	Chipped	-	7
	Right Front Fender	Multiple Dents/Paint Damage	-	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Door	Dent(S) W/ Paint Dmg	-	3 To 4 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.