Approved CR

IAA North Virginia
15 Le Way Drive
Branch No 723
Fredericksburg, VA 22406
(540) 373-7800/(540) 371-4123
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2009 INTERNATIONAL 4000**
Bodystyle/Series:	**- 4300**
Color:	**Blue**
Mileage:	**8,997 (Verified)**
Turn-in Mileage:	-
VIN:	**1HTJTSKM89H059693**
Work Order/ Stock Number:	**46481989**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G710237Y**
Vehicle Grade :	**Grade 2.2**
Remarks:	-
Announcements:	• Rust
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	-	A/C:	**No**
Engine:	**8-Cylinder Diesel**	Cruise Control:	**Yes**
Engine Size:	**6.4 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth/Vinyl /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	-
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - LF 10 / 10 R 22.5	Car Tire Size - LR 10 / 10 R 22.5	Car Tire Size - RR 10 / 10 R 22.5
Car Tire Size - RF 10 / 10 R 22.5	LF Tires - 20/32 inch	LR Tires - 20/32 inch
RF Tires - 20/32 inch	RR Tires - 20/32 inch	Tire Brand - Front Left - DYNATRAC
Tire Brand - Front Right - DYNATRAC	Tire Brand - Rear Left - DYNATRAC	Tire Brand - Rear Right - DYNATRAC
Tire Model - RR - DT340	Tire Model - RF - DT340	Tire Model - LR - DT340
Tire Model - LF - DT340		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Seat Center Front	Worn	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Running Board	Bent	-	4 To 5 Inches
	Front Metal Bumper Painted	Heavy Scratch	-	> 12 Inches
	Roof	Peeling	-	> 12 Inches
	Left Head Lamp	Faded	-	Repair Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Head Lamp	Faded	-	Repair Required
	Right Front Wheel	Rust	-	Repair Required
	Rear Metal Bumper Painted	Rust	-	> 12 Inches
	Left Front Wheel	Rust	-	Repair Required
	Inside Bed	Broken	-	Replacement Required
	Fuel Tank	Rust	-	Severe Damage

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.