Approved CR

IAA Oklahoma City
7300 N 1-35 Service RD
Branch No 421
Oklahoma City, OK 73121
(405) 475-0230/(405) 680-9204
WHOLESALE ASSESSMENT ONLY

| | |
|---|---|
| Make/Model: | **2021 CHEVROLET MALIBU** |
| Bodystyle/Series: | **4 Door Sedan FWD 1FL** |
| Color: | **White** |
| Mileage: | **89,691 (Verified)** |
| Turn-in Mileage: | - |
| VIN: | **1G1ZC5ST2MF084417** |
| Work Order/ Stock Number: | **46519960** |
| Customer: | GSA Fleet Vehicle Sales<br>1800 F Street NW<br>Washington, DC 20405<br>fleetsalessupport@gsa.gov |
| Client Stock #: | **G101993Y** |
| Vehicle Grade : | **Grade 3.8** |
| Remarks: | - |
| Announcements: | - |
| Certification : | - |
| Req. Prev. Repair Order: | - |




Drivable: Yes

## Equipment

| | | | |
|---|---|---|---|
| Transmission: | **Continuously Variable Transmission** | A/C: | **No** |
| Engine: | **4-Cylinder Gas** | Cruise Control: | **Yes** |
| Engine Size: | **1.5 L** | Pwr Steering: | **Yes** |
| Roof: | **Hard Top** | Pwr Locks: | **Yes** |
| Radio: | - | Pwr Windows | **Yes** |
| Interior - Type/Color: | **Cloth Interior /BLACK** | Rear Defroster: | **Yes** |
| Airbag: | **Driver Side Air Bag** | Tilt Steering: | **Yes** |
| Seats: | **Buckets** | Drive Type: | **Front Wheel Drive** |
| Seat Count: | - | Brakes: | **Anti Lock Brakes** |

## Equipment

Additional Equipment:

| | | |
|---|---|---|
| Car Tire Size - LF 205 / 65 R 16 | Car Tire Size - LR 205 / 65 R 16 | Car Tire Size - RR 205 / 65 R 16 |
| Car Tire Size - RF 205 / 65 R 16 | LF Tires - 7/32 inch | LR Tires - 10/32 inch |
| RF Tires - 6/32 inch | RR Tires - 10/32 inch | Tire Brand - Front Left - FIRESTONE |
| Tire Brand - Front Right - FIRESTONE | Tire Brand - Rear Left - KUMHO | Tire Brand - Rear Right - KUMHO |
| Tire Model - RR - Solus TA51A | Tire Model - RF - FT140 | Tire Model - LR - Solus TA51A |
| Tire Model - LF - FT140 | | |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Photo - Vin/Id Sticker | Photo Only | - | - |
|  | Engine | Photo Only | - | - |
|  | Keys | Photo Only | - | - |
|  | Front Cover Center | Photo Only | - | - |
|  | Right Side Panel | Photo Only | - | - |
|  | Left Side Panel | Photo Only | - | - |
|  | Instrument Panel | Photo Only | - | - |
|  | Rear Bumper | Photo Only | - | - |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Extra Photo 2 | Photo Only | - | - |
|  | Extra Photo 3 | Photo Only | - | - |
|  | Right Front Fender | Photo Only | - | - |
|  | Extra Photo 4 | Photo Only | - | - |
|   | Extra Photo 5 | Photo Only | - | - |
|  | Extra Photo 6 | Photo Only | - | - |
|  | Left Front Fender | Photo Only | - | - |
|  | Left Rear Bumper/Cover | Photo Only | - | - |
|  | Right Rear Bumper/Cover | Photo Only | - | - |
|  | Photo - Dash | Photo Only | - | - |
|  | Extra Photo 1 | Photo Only | - | - |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Odometer | Photo Only | - | - |
|  | Rear Seats | Photo Only | - | - |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Right Rear Wheel | Curb Rash | - | 1 To 2 Inches |
|  | Rear Bumper | Cracked Paint | - | 3 To 4 Inches |
|  | Left Rocker Panel | Heavy Scratch | - | 1/2 To 1 Inch |
|  | Front Bumper | Misaligned | - | Repair Required |
|  | Right Rear Door | Multiple Dents/No Paint Damage | - | 2 |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Hood | Heavy Scratch | - | 1/2 To 1 Inch |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.