



Approved CR

IAA Sioux Falls
47028 276th St
Branch No 362
Sioux Falls, SD 57104
(605)271-8855/(605)271-4662
WHOLESALE ASSESSMENT ONLY

Make/Model: **2022 NISSAN
ALTIMA**
Bodystyle/Series: **4 Door Sedan
S FWD**
Color: **Silver**
Mileage: **48,326
(Verified)**
Turn-in Mileage: **-**
VIN: **1N4BL4BV3NN383559**
Work Order/
Stock Number: **46279434**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G10-0026Z**
Vehicle Grade : **Grade 0.0**
Remarks: **-**
Announcements:

**• SALVAGE
TITLE**

Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: No

Equipment

Transmission:	Continuously Variable Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	-	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 215 / 60 R 16	Car Tire Size - RF 215 / 60 R 16	Car Tire Size - LF 215 / 60 R 16
Car Tire Size - LR 215 / 60 R 16	LF Tires - 10/32 inch	LR Tires - 10/32 inch
RF Tires - 10/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - HERCULES
Tire Brand - Front Right - HERCULES	Tire Brand - Rear Left - HERCULES	Tire Brand - Rear Right - HERCULES
Tire Model - LF - Roadtour Connect PCV	Tire Model - LR - Roadtour Connect PCV	Tire Model - RF - Roadtour Connect PCV
Tire Model - RR - Roadtour Connect PCV		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Rail	Kinked	-	1 To 2 Inches
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Apron	Kinked	-	1 To 2 Inches
	Core Support	Kinked	-	1 To 2 Inches
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Airbag - Front Left	Deployed	-	Replacement Required
	Left Knee Airbag	Deployed	-	Replacement Required
	Windshield	Broken	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof Panel	Hail Damage	-	3
	Left Side Curtain Air Bag	Deployed	-	Replacement Required
	Left Front Door	Misaligned	-	Repair Required
	Right Head Lamp	Broken	-	Replacement Required
	Right Front Fender	Dent(S) W/No Paint Dmg	-	9 To 10 Inches
	Left Front Fender	Severe Damage	-	Replacement Required

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Head Lamp	Missing	-	Replacement Required
	Front Bumper	Severe Damage	-	Replacement Required
	Grille	Broken	-	Replacement Required
	Hood	Severe Damage	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.