Approved CR

IAA Salt Lake City
1800 South 1100 West
Branch No 342
Ogden, UT 84401-0258
(801) 399-2818/(801) 393-2325
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2021 CHRYSLER VOYAGER**
Bodystyle/Series:	**Van LX**
Color:	**Silver**
Mileage:	**104,307 (Verified)**
Turn-in Mileage:	-
VIN:	**2C4RC1CG3MR568428**
Work Order/ Stock Number:	**46378812**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G410588Y**
Vehicle Grade :	**Grade 3.2**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth/Vinyl /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**3rd**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Anti Lock Brakes**

Equipment

Additional Equipment:

Car Tire Size - RR 235 / 65 R 17	Car Tire Size - RF 235 / 65 R 17	Car Tire Size - LF 235 / 65 R 17
Car Tire Size - LR 235 / 65 R 17	LF Tires - 5/32 inch	LR Tires - 7/32 inch
RF Tires - 5/32 inch	RR Tires - 9/32 inch	Tire Brand - Front Left - VREDESTEIN
Tire Brand - Front Right - VREDESTEIN	Tire Brand - Rear Left - VREDESTEIN	Tire Brand - Rear Right - VREDESTEIN
Tire Model - RR - Pinza At	Tire Model - LF - Pinza At	Tire Model - LR - Pinza At
Tire Model - RF - Pinza At		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning Light - Air Bag	On	-	Unacceptable
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Misaligned	-	Repair Required
	Left Front Door	Dent(S) W/ Paint Dmg	-	< 1/8 Inch
	Left Rear Door	Chipped	-	6
	Left Rear Marker Lamp	Misaligned	-	Repair Required
	Right Front Door	Multiple Dents/Paint Damage	-	2
	Front Bumper	Chipped	-	10 Or More

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Chipped	-	10 Or More
	Rear Bumper	Chipped	-	10 Or More

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.