Approved CR

Dealers Auto Auction of Cincinnati, LLC
120 City Centre Drive
Cincinnati, OH 45216
513-679-7910/513-679-7913
aschoenling@dealersauto.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2017 RAM 3500 CHASSIS CAB TRA**
Bodystyle/Series:	**Crew Cab -**
Color:	**WHITE**
Mileage:	**40,784 (Digital)**
Turn-in Mileage:	-
VIN:	**3C7WRTCJ3HG719808**
Work Order/ Stock Number:	**0051558**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**102620I2719808**
Vehicle Grade :	**Grade 2.9**
Remarks:	-
Announcements:	• ABS PROBLEMS RIDE & DRIVE
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**8-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**6.4 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**Vinyl Interior /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**No**
Seats:	**Bench**	Drive Type:	**4-Wheel Drive**
Seat Count:	**0**	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

Automatic Headlights	Auxiliary Audio Input	Bluetooth Connection
Car LF Tires - 10/32 inch	Car LR Tires - 6/32 inch	Car RF Tires - 8/32 inch
Car RR Tires - 5/32 inch	Car Tire Size - LF: LT235/80SR17 LR: LT235/80SR17 RF: LT235/80SR17 RR: LT235/80SR17 SP: FULL SIZE	Child Safety Locks
Cylinders - 8	Daytime Running Lights	Dual Rear Wheels
Electrochromic Rearview Mirror	Electronic Stability Control	Engine Immobilizer
Front Tow Hooks	Heated Mirrors	Ignition Key - 2key(s)
Intermittent Wipers	LF Tires - 10/32 inch	LR Tires - 6/32 inch
Limited Slip Differential	MP3 Radio	Pass. Air Bag
Passenger Air Bag Sensor	Passenger Vanity Mirror	Power Mirrors
RF Tires - 8/32 inch	RR Tires - 5/32 inch	Rear Bench Seat
Side Airbags - Front	Spare Tire - Full Size	Spare Wheel - Steel
Tilt Steering Wheel	Tire Brand - Front Left - NEXEN	Tire Brand - Front Right - NEXEN
Tire Brand - Rear Left - NEXEN	Tire Brand - Rear Right - NEXEN	Tire LF - 10/32 inch
Tire RF - 8/32 inch	Tire Size - LF: LT235/80SR17 LR: LT235/80SR17 RF: LT235/80SR17 RR: LT235/80SR17 SP: FULL SIZE	Tire Size - LF: LT235/80SR17 LR: LT235/80SR17 RF: LT235/80SR17 RR: LT235/80SR17 SP: FULL SIZE
Trip Computer	Turn Signal Mirrors	Wheels Front Left - Steel
Wheels Front Right - Steel	Wheels Rear Left - Steel	Wheels Rear Right - Steel

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Extra Photo 8	Photo Only	-	-
	Extra Photo 9	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
[no photo]	Front Bumper	Aftermarket	-	Acceptable
	Left Front Fender	Chipped	Refinish	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Rust	Repair	> 12 Inches
[no photo]	Pickup Bed	Aftermarket	-	Acceptable
	Pickup Bed	Rust	Report	> 12 Inches
[no photo]	Upper Engine	Noise	Mechanical Check	Repair Required
	Warning - Traction Control	On	Mechanical Check	Unacceptable
	Warning Light - Abs	On	Mechanical Check	Unacceptable

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.