



Approved CR

IAA Charleston
430 Tannenbaum Rd
Branch No 720
Ravenel, SC 29470
(843) 556-7620/(843) 571-3006
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD
TRANSIT
CONNECT**

Bodystyle/Series: **Wagon XL**

Color: **Blue**

Mileage: **26,809
(Verified)**

Turn-in Mileage: **-**

VIN: **NM0GE9E76J1352728**

Work Order/
Stock Number: **46390834**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G413047U**

Vehicle Grade : **Grade 3.1**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment


Additional Equipment:

Car Tire Size - RR 215 / 55 R 16	Car Tire Size - RF 215 / 55 R 16	Car Tire Size - LF 215 / 55 R 16
Car Tire Size - LR 215 / 55 R 16	LF Tires - 10/32 inch	LR Tires - 6/32 inch
RF Tires - 7/32 inch	RR Tires - 6/32 inch	Tire Brand - Front Left - HANKOOK
Tire Brand - Front Right - HANKOOK	Tire Brand - Rear Left - HANKOOK	Tire Brand - Rear Right - HANKOOK
Tire Model - LF - Ventus V12 Evo K110	Tire Model - LR - Ventus V12 Evo K110	Tire Model - RF - Ventus V12 Evo K110
Tire Model - RR - Ventus V12 Evo K110		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel Cover	Missing	-	Replacement Required
	Right Front Tire	Cut	-	Replacement Required
	Right Rear Door	Chipped	-	2
	Left Rear Wheel Cover	Peeling	-	7 To 8 Inches
	Left Front Wheel Cover	Missing	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Seat Molding	Cracked	-	Replacement Required
	Front Center Armrest	Torn	-	1 To 2 Inches
	Left Drip Rail	Chipped	-	3
	Left Rear St Back Trim Panel	Torn	-	> 12 Inches
	Left Rear Door	Multiple Scratches Light	-	4
	Left Front Door	Multiple Scratches Light	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Marker Lamp	Broken	-	Replacement Required
	Right Front Fender	Multiple Scratches Light	-	3
	Front Bumper Cover Upper	Peeling	-	> 12 Inches
	Left Head Lamp	Faded	-	Repair Required
	Right Head Lamp	Faded	-	Repair Required
	Hood	Chipped	-	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Light Scratch	-	1 To 2 Inches
	Right Front Wheel	Corrosion	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.