



Approved CR

IAA Miami-North
20499 Stirling Road
Branch No 736
Southwest Ranch, FL 33332
(954)680-4370/(954)680-4372
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD EXPLORER**
Bodystyle/Series: **Sport Utility Vehicle -**
Color: **Black**
Mileage: **61,572 (Verified)**
Turn-in Mileage: **-**
VIN: **1FM5K8BH5JGC45396**
Work Order/
Stock Number: **46378121**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G622933V**
Vehicle Grade : **Grade 4.0**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2.3 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /-	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	4th	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 245 / 60 R 18

Car Tire Size - LR 245 / 60 R 18

Car Tire Size - RR 245 / 60 R 18

Car Tire Size - RF 245 / 60 R 18

LF Tires - 8/32 inch

LR Tires - 9/32 inch

RF Tires - 8/32 inch

RR Tires - 6/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - GOODYEAR

Tire Brand - Rear Right - KELLY

Tire Model - RR - Edge A/S

Tire Model - RF - Destination LE3


Tire Model - LR - Assurance

Tire Model - LF - Destination LE3

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Warning - Tire Pressure	On	-	Unacceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Hood	Chipped	-	2
	Right Front Wheel	Curb Rash	-	1 To 2 Inches
	Right Rear Door	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Lift Gate	Chipped	-	3
	Left Qtr Panel	Chipped	-	2
	Left Front Wheel	Curb Rash	-	2 To 3 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Roof	Chipped	-	3
	Left Front Door Applique	Broken	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.